

Call 01 Slide Repair on I-55 Southbound South of Hazlehurst at Tower Road Interchange, known as Federal Aid Project No. STP-0055-01(119) / 108495301 in Covich County.

Q1. Can we get the soil boring results for this project?

A1. Soil borings were not done for this project.

Q2. Will the contractor be allowed to drive the piles by usage of a vibratory hammer, or will an impact hammer be required to drive the piles?

A2. Usage of a vibratory hammer will be allowed.

Q3. 605-W001 Filter Material for Combination Storm Drain and/or Underdrains, Type A, FM (GY) 1,100.0 CY: Drawing \$PG\$ notes "crushed stone" for this area. Is this material required to be crushed stone meeting the gradation requirements of 605-W001 Filter Material for Combination Storm Drain and/or Underdrains, Type A, FM, or will a washed gravel material be allowed?

A3. A washed gravel material will NOT be allowed. It states in Section H of the Scope of Work, "The drainage layer will be backfilled with 605-W001 – Filter Material for Underdrains, Type A, FM – Size #57."

Q4. Even though soil borings were not done for the project, does the Department have a soil profile that it anticipates to be in the location of the pile?

A4. No.