

Call 05 Bridge Joint Repair on various routes in Yazoo & Holmes Counties, known as Federal Aid Project No. BR-9999-03(006) / 106647302 in District 3.

Q1. Quantity on pay item 202-B298 does not match quantity for armor removal or compression seal. What material is this pay item pertaining to?

A1. The pay item pertains to Removal of Existing Joint Material for sliding plate joints and armor joints. The reason the quantity doesn't match exactly is that some of this material is already missing. In reference to compression joints, the removal of any existing material will be absorbed and is not measured for separate pay.