

Call 12 Bridge Repair on SR 178 over the Mantachie Canal Bridge No. 102.7, known as State Project No. EXB-2835-00(006) / 107139310 in Itawamba County

Q1. How thick is the layer of asphalt for the new pressure relief joints?

A1. Three (3) inches and variable.

Q2. On Sheet 8002, Note #4 in the scope of work description states, "Paint exposed surfaces of the existing T-beam bearings at repair locations. See painting notes." **1.** Is there a pay item for this work or is it incidental to Item 907-845-A002? **2.** How many total bearings need to be painted?

A2. **1.** It is absorbed work, no separate pay item. **2.** Thirty-two (32)

Q3. Does the existing paint on the steel structure contain lead?

A3. Yes