

Call 12 Bridge Repair on I-55 Bridge Nos. 96.3A & 96.3B, known as State Project No. EXB-0055-02(037) / 107139301 in Hinds County.

Q1. **1.** Can you provide more detail for the slope paving hole locations? **2.** Will MDOT provide cleaning of sloped concrete prior to grouting?

A1. **1.** No, the location of the holes shall be determined by the Contractor. **2.** No, cleaning the slope paving is addressed under clearing and grubbing (page no. 56 of the proposal.).

Q2. Can we use Type I cement grout in place of Type 6?

A2. No