

Call 01 Safety upgrades to MS 145 Corridor, known as Federal Aid Project Nos. HSIP-2839-00(018) / 106953301 & 302 in Lee County.

- Q1. The stone base will be placed at night under a lane closure and is paid for by the Ton. Will MDOT consider changing this to Cubic Yard so this material can be stockpiled and hauled to the project as needed and not have to be weighed from the contractor's stockpile?
- A1. See upcoming addendum.
- Q2. Will traffic be allowed to drive on the milled surface of the mainline and side roads? If so for how long?
- A2. See upcoming addendum.
- Q3. Is a new conflict monitor (MMU) required on 632-C001 Modify Existing Traffic Signal Cabinet Assembly?
- A3. Yes. Conflict monitors will be required for the signal cabinets that only require cabinet modifications. These are necessary to run the new controllers.