

Call 05 Seal and Overlay approximately 7 miles of SR 35 from JCT US 98 North to Cornerstone Church, known as Federal Aid Project No. STP-0037-01(063) / 107807301 in Marion County.

Q1. Will we be required to place asphalt underneath the guardrail even though they will not be replaced or will we pave to the face of the existing guardrail?

A1. Asphalt is required underneath the guardrail as noted on Sheets Numbers 12 through 14.