

Call 10 Bridge Repair on I-10 WB over the Pearl River (Bridge No. 0.0), known as State Project No. SP-0010-01(183) / 109322301 in Hancock County.

- Q1. Please clarify the correct length of removal of wingwall railing and construction of new wingwall railing.
- A1. To get the complete bridge end rail replaced, remove the remaining 6 ft. and replace the 16 ft. of bridge rail damage with new construction. Refer to Sheet No. 8004, "ELEVATION OF WINGWALL AND RAIL REPAIR AREA AT END BENT NO. 76". The hatched area shown represents the remaining wing wall railing to be removed.