

Call 12 Slide Repair on I-20, I-55, I-220, and US 25, known as Federal Aid Project Nos. NHPP-9999-05(027) / 107258301, 302, & 303 in Hinds, Madison, and Scott Counties.

Q1. The plan set summary of quantities indicates that one each of item 907-637-A001 Equipment Cabinet, Type B and item 907-637-B001 ITS Equipment Cabinet Modifications are required at Site 6 (LS-6, Sheet No. 41, pdf p.43 and following) and Site 4 (LS-4, Sheet No. 49, pdf p. 51 and following). However the plans, special provisions, etc. neither indicate where the cabinet is to be installed or utilized nor of what work the ITS Equipment Cabinet Modifications consist? Please advise or provide additional details.

A1. See upcoming addendum.

Q2. The plans do not have site specific details for ITS (fiber) mapping, fiber installation and splice locations, aerial support details/type, pull box locations, ITS cabinet locations, cabinet specifics such as mounting type and internal hardware requirements. We are unable to accurately determine absorbed costs without this information. Are site specific details available?

A2. See upcoming addendum.