

**Call 01 Bridge Repair (Bridge No. 68.1) on Country Club Road over US 49, known as Federal Aid Project No. STBG-8760-00(007) / 109146301 in Forrest County.**

Q1. Is engineered temporary support required at the location of splice plate repair?

A1. Engineered temporary supports will be required based on any construction loading applied to the bridge.

Q2. Do you have any as built drawings for the bridge?

A2. **Revised Answer:** As-built and shop drawings can be viewed at the following link:

<https://file-exchange.mdot.state.ms.us/dl/?f=923f3e6c8d01c86a42bdc41bf5e3f06bea049518>

**Replaces Previous Link:**~~<https://file-exchange.mdot.state.ms.us/dl/?f=7e5e9b306349ffad1e75fbf6ed15aed00e485a87>~~