

Call 11 Placement of Raised Pavement Markers on various routes throughout the District, known as State Project No. MP-5000-00(162) / 307930301 in District 5.

- Q1. On sheet three of the plans under general note eight, it refers to placement of the two-way clear markers. It states "At the discretion of the engineer, any encroachment of the granular material shoulder onto the asphalt pavement shall be bladed back in order to install the edgeline RPMs in their proper configuration. This operation shall be absorbed under other items bid." It's unrealistic to be able to identify which locations will require this type of cleaning and properly quantify the cost associated with this type of operation. Will the Department please provide additional clarification or remove this statement from the notes and agree to handle the cleaning internally?
- A1. Blading of the shoulders shall not be required for the entirety of each route, but solely in small, localized areas as determined by the Engineer. Bidders are advised to bid as per the plans.