

Call 09 Installation of an Intersection Conflict Warning System & Clearing at the intersection of SR 9 & SR 334, known as Federal Aid Project No. HSIP-0050-01(042) / 109485301 in Pontotoc County.

Q1. Can any permanent sign quantity sheets or plans be provided?

A1. See addendum.

Q2. Should pay item line # 0130 item code 638-A004 be installed on TSD-19H Flasher Assembly Pole?

A2. The Flasher Assembly Pole on TSD-19H should be utilized for 638-A004.

Q3. Can a Type B cabinet be used instead of the 632-A001 Type I Cabinet w/ Type 1 Controller since there are no traffic signals in this application?

A3. No.

Q4. On addendum no. 1 on note 3 under pay items, the "amber beacon, solar powered panel." The intersection layout sheet shows a 5C#12 cable being pulled to the beacons. Does MDOT want redundant power to the flashers?

A4. References to solar power are in error and are to be disregarded.