

Call 04 Bridge Repair on Browns Quarter Road over I-55 (Bridge No. 141.6), known as Federal Aid Project No. STBG-0055-02(280) / 109526301 in Holmes County.

Q1. On the replacement bearing assembly detail (page 77 of 163) the anchor plate is called out with a 0.375" x 0.75" welded retaining bar on 4 sides of the anchor plate. Is it acceptable to buy thicker anchor plate (2.25") and machine a "pocket" 0.375" deep in lieu of welding the bars?

A1. Yes, but drainage channels shall be cut into the thicker anchor plate in all four corners.

Q2. Can the as built drawings be made available for bridge number 141.6?

A2. As built drawings may be downloaded here: <https://file-exchange.mdot.state.ms.us/dl/?f=3fb23ed9f15d367880c647f9addbace4fa80ca04>