

Call 08 Bridge Replacement on Old Brandon Road (Bridge No. 48.6), known as Federal Aid Project No. BR-7272-00(008) / 106115301 in Rankin County.

Q1. 626.03.3 Retroreflectivity Requirements. Will retroreflectivity measurements be required on this project?

A1. No.

Q2. Sheet number SQS-1 and Sheet number 8005 indicate that the entire length of the existing timber pile is to be removed. Should an existing deteriorated timber pile break below the ground elevation. Will the department allow the alignment of the new bridge to be shifted so that the old pile do not conflict with the new pile? If no, what would be the departments solution to installing the new pile with a possible piece of old pile significantly below ground elevation?

A2. If existing piles cannot be completely pulled out, the new piles will be driven through them.