

Call 12 Bridge Repairs on Old US 11 over I-59 (Bridge No. 47.9) & Richburg Road over I-59 (Bridge Nos. 61.9A, & 61.9B), known as Federal Aid Project No. STBG-9999-06(405) / 109670301 in Lamar County.

Q1. Please upload drawings for Bearing Replacements.

A1. See Addendum 1.

Q2. Can MDOT add the locations of the FRP?

A2. See Addendum 1.

Q3. Can the as-builts be provided?

A3. They can be downloaded at the following link: <https://file-exchange.mdot.state.ms.us/dl/?f=6e5e4b24b66f79228a569ace1c946d04f2c33086>

Q4. Will MDOT allow full bridge closures for the installation of the PCSS?

A4. No. One lane of traffic must be maintained with a flagging operation until the PCSS cures.

Q5. The bearing pad drawing issued in the addendum shows that bridge 12281 has pad replacements for both the 50' (LP1) & 70' (LP2) spans. Please provide a breakdown of each as the drawings don't show the bridge layout.

A5. The bearing pad layout for Bridge 12281 can be downloaded at the following link: <https://file-exchange.mdot.state.ms.us/dl/?f=bf55490e631348da7154ff3007d8dbad8c0bd70f>