

Call 03 Mill & Overlay on I-55 ramps at the SR 463 interchange, known as Federal Aid Project No. IM-0055-02(285) / 109878301 in Madison County.

Q1. 626.03.3 Retroreflectivity Requirements: Will retroreflectivity measurements be required on this project?

A1. No.

Q2. The base repair table on page 92 list the tonnage of 12.5mm,HT Polymer mix required as 2,978.80 tons. The bid quantity is 3,430 tons. Why is the bid quantity different from the table?

A2. The base repair table does not account for the leveling required for the southwest ramp as shown on Page 78 of the proposal. The bid quantity of 3,430 tons is correct.

Q3. In regards to the pay item 907-630-O004 Remove and Reset Signs. Can a list of what signs will be removed and reset be provided?

A3. This pay item has been deleted. See Addendum 1. It is estimated that there is 1 Yield sign on a breakaway post, 5 post mounted delineators and 1 Pick it up MS/\$250 fine sign. These are to be absorbed as stated in the Scope of Work.