

Call 10 Bridge Repair on Franklin Road over I-55 (Bridge No. 147.4) & on Old Wilson Road over I-55 (Bridge No. 160.9), known as Federal Aid Project No. STBG-9999-03(402) / 109690301 in Holmes County.

Q1. Can MDOT please provide As-Built drawings?

A1. They can be downloaded at the following link: <https://file-exchange.mdot.state.ms.us/dl/?f=1cc061a6ce81ba9ceeb06bae9c4853d65a8d433e>

Q2. Can MDOT please provide a bearing placement plan layout/detail for each bridge location. Sheet 83 has general information on the replacement bearings for both bridges, but it does not include a bearing layout plan. This detail will be helpful to make sure suppliers quote the correct quantity of each type of pad.

A2. See Addendum 1.

Q3. Will the Department accept a 2-layer, 3/8" minimum thickness, light weight epoxy polymer surface system used in Arkansas, and Louisiana as an alternate to the polymer cement surface system?

A3. Bidders are advised to bid as per the Contract Documents.

Q4. Please provide as built, or at minimum the beam count for each replacement span so the proper number of bearing pads can be determined.

A4. See Answers #1 and #2.

Q5. Can we request as-builts for this project?

A5. See Answer #1.