

Itawamba Bridge repair on US Highway 78, 2.2 miles west of Junction 23/78, known as Maintenance Project No. MRP-1078-29(015) / 302788, in the County of Itawamba, State of Mississippi.				MISSISSIPPI DEPARTMENT OF TRANSPORTATION	KEY, LLC	TALBOT BROS. CONTR. CO. INC.			
				506,770.75	332,893.50	452,924.50	0.00	0.00	0.00
REF#	SM	ITEM DESCRIPTION	ITEM QUANTITY UNITS		1	2	3	4	5
10	202-B004	Removal of Asphalt Paved Shoulders, All Depths	433.000 SY		10.0000	12.0000	0.0000	0.0000	0.0000
20	202-B102	Removal of Guard Rail	175.000 LF		10.0000	10.0000	0.0000	0.0000	0.0000
30	202-B066	Removal of Raised Reflective Pavement Marker	49.000 E		10.0000	10.0000	0.0000	0.0000	0.0000
40	202-B076	Removal of Traffic Stripe	4,745.000 LF		1.5000	1.5000	0.0000	0.0000	0.0000
50	403-C001	Hot Mix Asphalt, HT, 19-mm mixture, Trench Widening	30.000 T		250.0000	200.0000	0.0000	0.0000	0.0000
60	606-B001	Guard Rail, Class A, Type 1	175.000 LF		20.0000	20.0000	0.0000	0.0000	0.0000
70	606-D008	Guard Rail, Bridge End Section, Type H	1.000 E		1,000.0000	1,000.0000	0.0000	0.0000	0.0000
80	606-E001	Guard Rail, Terminal End Section	1.000 E		2,500.0000	2,500.0000	0.0000	0.0000	0.0000
90	618-B001	Additional Construction Signs	1.000 SF		10.0000	10.0000	0.0000	0.0000	0.0000
100	619-A1007	Temporary Traffic Stripe, Continuous White, Type 1 Tape	5,565.000 LF		1.9500	1.9500	0.0000	0.0000	0.0000
110	619-A2007	Temporary Traffic Stripe, Continuous Yellow, Type 1	3,605.000 LF		1.9500	1.9500	0.0000	0.0000	0.0000
120	625-C002	Traffic Stripe, Continuous White	1.000 MI		1,000.0000	1,000.0000	0.0000	0.0000	0.0000
130	625-D002	Traffic Stripe, Continuous Yellow	1.000 MI		1,000.0000	1,000.0000	0.0000	0.0000	0.0000
140	627-K001	Red-Clear Reflective High Performance Raised Markers	52.000 E		10.0000	10.0000	0.0000	0.0000	0.0000
150	628-I002	6" High Performance Cold Plastic Traffic Stripe, Skip	2,055.000 LF		2.5000	2.5000	0.0000	0.0000	0.0000
160	628-J002	6" High Performance Cold Plastic Traffic Stripe,	423.000 LF		6.0000	6.0000	0.0000	0.0000	0.0000
170	628-M002	6" High Performance Cold Plastic Traffic Stripe,	423.000 LF		6.0000	6.0000	0.0000	0.0000	0.0000
180	630-F002	Delineators, Guard Rail, Yellow	7.000 E		18.0000	18.0000	0.0000	0.0000	0.0000
190	630-G003	Type 3 Object Markers, OM-3L, Post Mounted	1.000 E		70.0000	70.0000	0.0000	0.0000	0.0000
200	907-824-PP0	Bridge Repair, Pressure Wash Bent 6L & Span 5L and 6L,	0.000 LS		7,500.0000	18,000.0000	0.0000	0.0000	0.0000
210	907-824-PP0	Bridge Repair, Remove Steel Stay-In-Place Forms, Per	1,455.000 SF		7.0000	10.0000	0.0000	0.0000	0.0000
220	907-824-PP0	Bridge Repair, Repl. Beams, Brng Pads, Br Railing and	0.000 LS		60,000.0000	90,000.0000	0.0000	0.0000	0.0000
230	907-824-PP0	Bridge Repair, Repl. Beams, Brng Pads, Br Railing and	0.000 LS		65,000.0000	90,000.0000	0.0000	0.0000	0.0000
240	907-824-PP0	Bridge Repair, Repair Damaged Concrete Riser Cap at	0.000 LS		5,000.0000	14,000.0000	0.0000	0.0000	0.0000
250	907-824-PP0	Bridge Repair, Repair Damaged Concrete Pile Encasement	1.000 E		5,000.0000	10,000.0000	0.0000	0.0000	0.0000
260	907-824-PP0	Bridge Repair, Repair Damaged Bridge Rail in Span 7L,	0.000 LS		7,000.0000	12,000.0000	0.0000	0.0000	0.0000
270	907-824-PP0	Bridge Repair, Repair Damaged Bridge Deck, Per Plans	120.000 SF		135.0000	75.0000	0.0000	0.0000	0.0000
280	618-A001	Maintenance of Traffic	0.000 LS		65,000.0000	104,000.0000	0.0000	0.0000	0.0000
290	620-A001	Mobilization	0.000 LS		33,000.0000	33,000.0000	0.0000	0.0000	0.0000