

Work necessary to Repair the Hail Damage to the Whitfield Offices, known as State Project Nos. BWO-5137-61(002), BWO-5051-61(002), BWO-5150-61(002), BWO-5188-61(002), & BWO-5031-61(003) / 502907301 ,302, 303, 304, & 305 in Rankin County.					Sullivan Enterprises, Inc.	Independent Roofing Systems, Inc.	M & S Roofing Co., Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$280,000.00					\$190,300.00	\$216,504.00	\$218,000.00
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	1560-A001	Repair of Existing Project Office Roof Existing Project Office Roof	1.000	LS	83,000.00	107,016.00	97,000.00
0020	1560-A001	Repair of Existing Old Project Office Roof Existing Old Project Office Roof	1.000	LS	22,000.00	23,420.00	26,000.00
0030	1560-A001	Repair of Existing Storage Building Roof Existing Storage Building Roof	1.000	LS	7,300.00	9,408.00	11,500.00
0040	1560-A001	Repair of Existing Maintenance Offices Roof Existing Maintenance Offices Roof	1.000	LS	29,000.00	49,392.00	43,000.00
0050	1560-A001	Repair of Existing Maintenance Shop Building Roof Existing Maintenance Shop Building Roof	1.000	LS	49,000.00	27,268.00	40,500.00

Letting Date: 9/22/2015

Call Number: 08

Page 1 of 1

Work necessary to Repair the Hail Damage to the Whitfield Offices, known as State Project Nos. BWO-5137-61(002), BWO-5051-61(002), BWO-5150-61(002), BWO-5188-61(002), & BWO-5031-61(003) / 502907301 ,302, 303, 304, & 305 in Rankin County.					Industrial Roofing & Construction	Roofing Solutions, LLC	
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$280,000.00					\$257,370.00	<b>IRREGULAR</b> \$336,340.00	
Ref#	Item	Item Description	Item Qty	Units	4	5	
0010	1560-A001	Repair of Existing Project Office Roof Existing Project Office Roof	1.000	LS	101,069.00	117,860.00	
0020	1560-A001	Repair of Existing Old Project Office Roof Existing Old Project Office Roof	1.000	LS	36,944.00	55,850.00	
0030	1560-A001	Repair of Existing Storage Building Roof Existing Storage Building Roof	1.000	LS	15,186.00	23,260.00	
0040	1560-A001	Repair of Existing Maintenance Offices Roof Existing Maintenance Offices Roof	1.000	LS	47,715.00	53,550.00	
0050	1560-A001	Repair of Existing Maintenance Shop Building Roof Existing Maintenance Shop Building Roof	1.000	LS	56,456.00	85,820.00	

Letting Date: 9/22/2015

Call Number: 08

Page 1 of 1