

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties.					Century Construction & Realty, Inc.	Tanner Construction Company, Inc.	Key, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$1,928,189.80					\$3,770,285.12	\$3,949,726.00	\$3,983,731.00
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	234-A001	Temporary Silt Fence	1,500.000	LF	6.07	5.00	5.00
0020	235-A001	Temporary Erosion Checks	50.000	BALE	18.22	15.00	15.00
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	46.000	SF	8.50	18.00	4.00
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	184.000	SF	8.50	18.00	4.00
0050	619-G4005	Barricades, Type III, Double Faced	24.000	LF	17.00	26.00	18.00
0060	619-G7001	Warning Lights, Type "B"	2.000	EA	224.00	270.00	100.00
0070	620-A001	Mobilization	1.000	LS	907,000.00	380,000.00	340,000.00
0080	907-225-A001	Grassing	1.000	ACRE	3,000.00	2,500.00	2,500.00
0090	907-226-A001	Temporary Grassing	1.000	ACRE	1,822.00	1,500.00	1,500.00
0100	907-234-C002	Super Silt Fence	500.000	LF	12.15	10.00	10.00
0110	907-237-A002	Wattles, 12"	200.000	LF	6.07	5.00	5.00
0120	907-618-A001	Maintenance of Traffic	1.000	LS	750,000.00	120,000.00	320,000.00
0130	202-B298	Removal of Existing Joint Material	104.000	LF	47.00	50.00	100.00
0140	808-A001	Joint Preparation	1,560.000	LF	10.21	7.00	11.00
0150	907-823-A001	Preformed Joint Seal, Type I	728.000	LF	55.00	28.00	44.00
0160	907-823-A002	Preformed Joint Seal, Type II	52.000	LF	63.55	35.00	66.00
0170	907-823-B001	Saw Cut, Type I	1,456.000	LF	9.84	8.00	2.50
0180	907-823-B002	Saw Cut, Type II	104.000	LF	31.72	10.00	5.00
0190	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 3' Support Plate, Per Plans	33.000	EA	2,238.00	11,270.00	10,000.00
0200	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 4' Support Plate, Per Plans	76.000	EA	2,300.00	11,270.00	10,000.00
0210	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 5' Support Plate, Per Plans	19.000	EA	2,350.00	11,270.00	10,000.00
0220	907-824-PP095	Bridge Repair, Repair end of Degraded 30' Steel Girder with 6' Support Plate, Per Plans	2.000	EA	2,413.00	11,270.00	10,000.00
0230	907-824-PP095	Bridge Repair, Replace Bottom Flange Cover Plate of Steel Girder, Per Plans	3.000	EA	15,200.00	100,000.00	100,000.00
0240	907-824-PP095	Bridge Repair, Re-weld Riser to Bottom of 30' Steel Girder, Per Plans	2.000	EA	13,900.00	3,000.00	20,000.00
0250	907-824-PP097	Bridge Repair, Concrete Encasement for Piling at Bents 2, 3, & 5 thru 29, Per Plans	1,379.000	LF	554.00	700.00	650.00
0260	907-824-PP097	Bridge Repair, Fill Intermediate Bridge Deck Joints, Per Plans	104.000	LF	121.00	200.00	100.00

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties.					Century Construction & Realty, Inc.	Tanner Construction Company, Inc.	Key, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$1,928,189.80					\$3,770,285.12	\$3,949,726.00	\$3,983,731.00
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0270	907-824-PP097	Bridge Repair, Structural Concrete Encasement for Piling at Bent 4, Per Plans	235.000	LF	1,945.00	700.00	775.00
0280	907-824-PP098	Bridge Repair, Painting of Steel Structure, Per Plans	9,340.000	SF	30.40	44.00	43.00
0290	907-824-PP101	Bridge Repair, Repair Spalled Concrete with Epoxy Mortar, Per Plans	85.000	CF	1,382.00	500.00	1,250.00

Letting Date: 3/22/2016

Call Number: 10

Page 2 of 2