

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties.					OCCI, Inc.	Gibson & Associates, Inc.	Century Construction & Realty, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$3,199,464.80					\$2,798,930.00	\$3,394,159.50	\$3,744,261.50
Ref#	Item	Item Description	Item Qnty	Units	1	2	3
0010	234-A001	Temporary Silt Fence	1,500.000	LF	10.00	1.00	6.15
0020	235-A001	Temporary Erosion Checks	50.000	BALE	50.00	10.00	18.44
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	46.000	SF	20.00	8.75	9.22
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	184.000	SF	20.00	8.75	9.22
0050	619-G4005	Barricades, Type III, Double Faced	24.000	LF	30.00	19.80	19.67
0060	619-G7001	Warning Lights, Type "B"	2.000	EA	250.00	181.50	227.45
0070	620-A001	Mobilization	1.000	LS	270,000.00	331,000.00	373,000.00
0080	907-234-C002	Super Silt Fence	500.000	LF	10.00	1.00	15.36
0090	907-237-A002	Wattles, 12"	200.000	LF	50.00	10.00	12.30
0100	907-618-A001	Maintenance of Traffic	1.000	LS	355,000.00	316,000.00	375,000.00
0110	202-B298	Removal of Existing Joint Material	104.000	LF	40.00	110.00	49.90
0120	808-A001	Joint Preparation	1,560.000	LF	40.00	16.50	10.91
0130	907-823-A001	Preformed Joint Seal, Type I	728.000	LF	150.00	33.00	57.78
0140	907-823-A002	Preformed Joint Seal, Type II	52.000	LF	160.00	44.00	66.39
0150	907-823-B001	Saw Cut, Type I	1,456.000	LF	50.00	8.80	10.31
0160	907-823-B002	Saw Cut, Type II	104.000	LF	250.00	11.00	33.56
0170	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 3' Support Plate, Per Plans	33.000	EA	5,200.00	4,650.00	3,500.00
0180	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 4' Support Plate, Per Plans	76.000	EA	6,400.00	6,200.00	3,500.00
0190	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 5' Support Plate, Per Plans	19.000	EA	7,700.00	7,750.00	3,600.00
0200	907-824-PP095	Bridge Repair, Repair end of Degraded 30' Steel Girder with 6' Support Plate, Per Plans	2.000	EA	8,800.00	9,300.00	3,000.00
0210	907-824-PP095	Bridge Repair, Replace Bottom Flange Cover Plate of Steel Girder, Per Plans	3.000	EA	30,000.00	42,500.00	20,000.00
0220	907-824-PP095	Bridge Repair, Re-weld Riser to Bottom of 30' Steel Girder, Per Plans	2.000	EA	3,000.00	2,000.00	5,000.00
0230	907-824-PP097	Bridge Repair, Concrete Encasement for Piling at Bents 2, 3, & 5 thru 29, Per Plans	1,379.000	LF	470.00	800.00	800.00
0240	907-824-PP097	Bridge Repair, Fill Intermediate Bridge Deck Joints, Per Plans	104.000	LF	50.00	160.00	250.00
0250	907-824-PP097	Bridge Repair, Structural Concrete Encasement for Piling at Bent 4, Per Plans	235.000	LF	710.00	750.00	3,000.00
0260	907-824-PP098	Bridge Repair, Painting of Steel Structure, Per Plans	9,340.000	SF	10.00	28.00	40.00

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties.					OCCI, Inc.	Gibson & Associates, Inc.	Century Construction & Realty, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$3,199,464.80					\$2,798,930.00	\$3,394,159.50	\$3,744,261.50
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0270	907-824-PP101	Bridge Repair, Repair Spalled Concrete with Epoxy Mortar, Per Plans	85.000	CF	250.00	2,150.00	1,800.00

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties.					Key, LLC		
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$3,199,464.80					\$4,139,731.00		
Ref#	Item	Item Description	Item Qnty	Units	4		
0010	234-A001	Temporary Silt Fence	1,500.000	LF	5.00		
0020	235-A001	Temporary Erosion Checks	50.000	BALE	15.00		
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	46.000	SF	4.00		
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	184.000	SF	4.00		
0050	619-G4005	Barricades, Type III, Double Faced	24.000	LF	18.00		
0060	619-G7001	Warning Lights, Type "B"	2.000	EA	100.00		
0070	620-A001	Mobilization	1.000	LS	500,000.00		
0080	907-234-C002	Super Silt Fence	500.000	LF	10.00		
0090	907-237-A002	Wattles, 12"	200.000	LF	5.00		
0100	907-618-A001	Maintenance of Traffic	1.000	LS	320,000.00		
0110	202-B298	Removal of Existing Joint Material	104.000	LF	100.00		
0120	808-A001	Joint Preparation	1,560.000	LF	11.00		
0130	907-823-A001	Preformed Joint Seal, Type I	728.000	LF	44.00		
0140	907-823-A002	Preformed Joint Seal, Type II	52.000	LF	66.00		
0150	907-823-B001	Saw Cut, Type I	1,456.000	LF	2.50		
0160	907-823-B002	Saw Cut, Type II	104.000	LF	5.00		
0170	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 3' Support Plate, Per Plans	33.000	EA	10,000.00		
0180	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 4' Support Plate, Per Plans	76.000	EA	10,000.00		
0190	907-824-PP095	Bridge Repair, Repair End of Degraded 30' Steel Girder with 5' Support Plate, Per Plans	19.000	EA	10,000.00		
0200	907-824-PP095	Bridge Repair, Repair end of Degraded 30' Steel Girder with 6' Support Plate, Per Plans	2.000	EA	10,000.00		
0210	907-824-PP095	Bridge Repair, Replace Bottom Flange Cover Plate of Steel Girder, Per Plans	3.000	EA	100,000.00		
0220	907-824-PP095	Bridge Repair, Re-weld Riser to Bottom of 30' Steel Girder, Per Plans	2.000	EA	20,000.00		
0230	907-824-PP097	Bridge Repair, Concrete Encasement for Piling at Bents 2, 3, & 5 thru 29, Per Plans	1,379.000	LF	650.00		
0240	907-824-PP097	Bridge Repair, Fill Intermediate Bridge Deck Joints, Per Plans	104.000	LF	100.00		
0250	907-824-PP097	Bridge Repair, Structural Concrete Encasement for Piling at Bent 4, Per Plans	235.000	LF	775.00		
0260	907-824-PP098	Bridge Repair, Painting of Steel Structure, Per Plans	9,340.000	SF	43.00		

Bridge Repair on SR 25 Across Bull Mountain Creek Bridge No. 147.1, known as State Project Nos. EXB-0040-02(036) / 1071393090 & 1071393091 in Itawamba & Monroe Counties. MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$3,199,464.80					Key, LLC		
					\$4,139,731.00		
Ref#	Item	Item Description	Item Qnty	Units	4		
0270	907-824-PP101	Bridge Repair, Repair Spalled Concrete with Epoxy Mortar, Per Plans	85.000	CF	1,250.00		