

Call 04 Bridge Repair on I-20 West to US 61 South Ramp, known as Federal Aid Project No. BR-0020-01(241) / 107398301000 Warren County.

Q1. Can the high friction deck coat be applied by hand or will the mechanical application be required?

A1. A high friction deck coat is not required on this project.

Q2. **1.)** Can the sections of the bridge to be painted be replaced with an encapsulating approved paint? **2.)** On the pay item 619-F4001 for the Concrete Barrier, is that quantity for only one phase of construction or is that to be absorbed into both phases. Could there be a remove and reset concrete median barrier pay item for phase 2 of construction?

A2. **1.)** Encapsulating paint may be used if approved by Bridge Division prior to beginning work. **2.)** See upcoming addendum.

Q3. How will the MDOT pay for remove and reset of the concrete median barriers from Phase 1 to Phase 2?

A3. See upcoming addendum.