

Bridge Painting on I-20 & I-55 at the Pearl River, known as Federal Aid Project Nos. BR-0055-02(247) / 107402301 & STP-0020-01 (222) / 107138307 in Rankin & Hinds Counties.					Klicos Painting Company, Inc.	Seminole Equipment , Inc.	Elite Industrial Painting, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$2,990,753.15					IRREGULAR		
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	189.000	SF	8.00	3.00	5.00
0020	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,544.000	SF	6.00	3.00	5.00
0030	619-E1001	Flashing Arrow Panel, Type C	7.000	EA	500.00	500.00	940.00
0040	619-G4001	Barricades, Type III, Single Faced	156.000	LF	15.00	1.00	30.00
0050	619-G5001	Free Standing Plastic Drums	429.000	EA	5.00	2.00	27.00
0060	619-G7001	Warning Lights, Type "B"	64.000	EA	50.00	2.00	270.00
0070	620-A001	Mobilization	1.000	LS	65,000.00	60,000.00	125,000.00
0080	907-618-A001	Maintenance of Traffic	1.000	LS	25,000.00	150,000.00	123,001.00
0090	907-619-E3001	Changeable Message Sign	10.000	EA	1,750.00	1,000.00	6,780.00
0100	202-B298	Removal of Existing Joint Material	1,051.000	LF	12.00	32.00	45.00
0110	202-B307	Removal of Bridge Deck	43.000	SY	2,500.00	255.00	255.00
0120	808-A001	Joint Preparation	5,575.000	LF	16.00	22.00	20.00
0130	907-804-A001	Bridge Concrete, Class AA	9.000	CY	1,500.00	5,500.00	5,500.00
0140	907-823-A001	Preformed Joint Seal, Type I	2,576.000	LF	28.00	32.00	35.00
0150	907-823-A002	Preformed Joint Seal, Type II	211.000	LF	35.00	42.00	40.00
0160	907-823-B001	Saw Cut, Type I	4,956.000	LF	9.00	12.00	8.00
0170	907-823-B002	Saw Cut, Type II	423.000	LF	14.00	10.00	10.00
0180	907-824-PP095	Bridge Repair, Base Plate Replacement	34.000	EA	2,500.00	4,850.00	4,850.00
0190	907-824-PP095	Bridge Repair, Bearing Replacement	12.000	EA	2,750.00	3,300.00	3,300.00
0200	907-824-PP095	Bridge Repair, Pressure Wash and Clean Bent	58.000	EA	2,500.00	750.00	1,050.00
0210	907-824-PP101	Bridge Repair, Epoxy Repair	28.000	CF	1,700.00	1,950.00	1,950.00
0220	907-845-A002	Coating Existing Structural Steel	1.000	LS	925,000.00	910,000.00	888,040.00

Bridge Painting on I-20 & I-55 at the Pearl River, known as Federal Aid Project Nos. BR-0055-02(247) / 107402301 & STP-0020-01 (222) / 107138307 in Rankin & Hinds Counties.					Elite Contractors, Inc.	Panther Industrial Painting, LLC	Olympus Painting Contractors, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$2,990,753.15					\$1,953,588.00	\$1,976,681.00	\$2,291,976.75
Ref#	Item	Item Description	Item Qty	Units	4	5	6
0010	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	189.000	SF	7.00	1.00	15.00
0020	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,544.000	SF	7.00	5.00	14.00
0030	619-E1001	Flashing Arrow Panel, Type C	7.000	EA	2,857.00	100.00	3,500.00
0040	619-G4001	Barricades, Type III, Single Faced	156.000	LF	12.00	1.00	18.00
0050	619-G5001	Free Standing Plastic Drums	429.000	EA	28.00	1.00	46.00
0060	619-G7001	Warning Lights, Type "B"	64.000	EA	31.25	1.00	165.00
0070	620-A001	Mobilization	1.000	LS	220,000.00	130,000.00	145,000.00
0080	907-618-A001	Maintenance of Traffic	1.000	LS	72,000.00	150,000.00	245,000.00
0090	907-619-E3001	Changeable Message Sign	10.000	EA	2,500.00	1,000.00	6,500.00
0100	202-B298	Removal of Existing Joint Material	1,051.000	LF	45.00	160.00	56.00
0110	202-B307	Removal of Bridge Deck	43.000	SY	255.00	275.00	185.00
0120	808-A001	Joint Preparation	5,575.000	LF	20.00	10.00	9.25
0130	907-804-A001	Bridge Concrete, Class AA	9.000	CY	5,500.00	6,500.00	5,500.00
0140	907-823-A001	Preformed Joint Seal, Type I	2,576.000	LF	35.00	35.00	37.00
0150	907-823-A002	Preformed Joint Seal, Type II	211.000	LF	40.00	50.00	50.00
0160	907-823-B001	Saw Cut, Type I	4,956.000	LF	8.00	8.00	9.00
0170	907-823-B002	Saw Cut, Type II	423.000	LF	10.00	10.00	10.00
0180	907-824-PP095	Bridge Repair, Base Plate Replacement	34.000	EA	4,850.00	5,500.00	4,600.00
0190	907-824-PP095	Bridge Repair, Bearing Replacement	12.000	EA	3,300.00	3,600.00	3,450.00
0200	907-824-PP095	Bridge Repair, Pressure Wash and Clean Bent	58.000	EA	275.00	1,000.00	1,206.00
0210	907-824-PP101	Bridge Repair, Epoxy Repair	28.000	CF	1,950.00	1,800.00	1,950.00
0220	907-845-A002	Coating Existing Structural Steel	1.000	LS	951,786.00	900,000.00	1,110,000.00

Bridge Painting on I-20 & I-55 at the Pearl River, known as Federal Aid Project Nos. BR-0055-02(247) / 107402301 & STP-0020-01 (222) / 107138307 in Rankin & Hinds Counties.					Gemstone, LLC	Blastech Enterprises, Inc.	M & J Construction Company of Pinellas County, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$2,990,753.15					\$2,381,106.44	IRREGULAR \$2,587,211.00	\$2,649,711.25
Ref#	Item	Item Description	Item Qty	Units	7	8	9
0010	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	189.000	SF	7.70	7.00	7.67
0020	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,544.000	SF	7.70	7.00	7.67
0030	619-E1001	Flashing Arrow Panel, Type C	7.000	EA	3,465.00	2,100.00	2,360.00
0040	619-G4001	Barricades, Type III, Single Faced	156.000	LF	13.20	17.00	17.70
0050	619-G5001	Free Standing Plastic Drums	429.000	EA	30.80	50.00	53.10
0060	619-G7001	Warning Lights, Type "B"	64.000	EA	165.00	100.00	100.30
0070	620-A001	Mobilization	1.000	LS	150,000.00	175,000.00	322,700.00
0080	907-618-A001	Maintenance of Traffic	1.000	LS	52,000.00	200,000.00	169,000.00
0090	907-619-E3001	Changeable Message Sign	10.000	EA	7,920.00	5,800.00	6,490.00
0100	202-B298	Removal of Existing Joint Material	1,051.000	LF	182.30	48.00	53.10
0110	202-B307	Removal of Bridge Deck	43.000	SY	280.50	270.00	300.90
0120	808-A001	Joint Preparation	5,575.000	LF	7.70	23.00	23.60
0130	907-804-A001	Bridge Concrete, Class AA	9.000	CY	6,050.00	5,800.00	6,490.00
0140	907-823-A001	Preformed Joint Seal, Type I	2,576.000	LF	34.10	38.00	41.30
0150	907-823-A002	Preformed Joint Seal, Type II	211.000	LF	59.40	43.00	47.20
0160	907-823-B001	Saw Cut, Type I	4,956.000	LF	8.80	9.00	9.44
0170	907-823-B002	Saw Cut, Type II	423.000	LF	9.08	10.00	11.80
0180	907-824-PP095	Bridge Repair, Base Plate Replacement	34.000	EA	5,335.00	5,000.00	5,723.00
0190	907-824-PP095	Bridge Repair, Bearing Replacement	12.000	EA	3,630.00	3,500.00	3,894.00
0200	907-824-PP095	Bridge Repair, Pressure Wash and Clean Bent	58.000	EA	1,200.00	700.00	800.00
0210	907-824-PP101	Bridge Repair, Epoxy Repair	28.000	CF	2,145.00	2,000.00	2,301.00
0220	907-845-A002	Coating Existing Structural Steel	1.000	LS	1,233,000.00	1,390,000.00	1,252,350.00

Bridge Painting on I-20 & I-55 at the Pearl River, known as Federal Aid Project Nos. BR-0055-02(247) / 107402301 & STP-0020-01 (222) / 107138307 in Rankin & Hinds Counties.					Southern Road & Bridge, LLC	Royal Bridge, Inc.	Monoko, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$2,990,753.15					\$2,697,546.00	\$2,827,400.50	\$2,897,609.00
Ref#	Item	Item Description	Item Qty	Units	10	11	12
0010	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	189.000	SF	1.00	5.00	1.00
0020	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,544.000	SF	1.00	5.00	0.10
0030	619-E1001	Flashing Arrow Panel, Type C	7.000	EA	500.00	970.00	10.00
0040	619-G4001	Barricades, Type III, Single Faced	156.000	LF	12.00	30.00	1.00
0050	619-G5001	Free Standing Plastic Drums	429.000	EA	5.00	27.00	0.50
0060	619-G7001	Warning Lights, Type "B"	64.000	EA	5.00	270.00	1.00
0070	620-A001	Mobilization	1.000	LS	200,000.00	300,000.00	100,000.10
0080	907-618-A001	Maintenance of Traffic	1.000	LS	250,000.00	131,980.00	20,000.00
0090	907-619-E3001	Changeable Message Sign	10.000	EA	100.00	6,780.00	10.00
0100	202-B298	Removal of Existing Joint Material	1,051.000	LF	50.00	51.00	166.00
0110	202-B307	Removal of Bridge Deck	43.000	SY	300.00	110.00	255.00
0120	808-A001	Joint Preparation	5,575.000	LF	30.00	23.00	7.00
0130	907-804-A001	Bridge Concrete, Class AA	9.000	CY	6,500.00	8,030.00	5,500.00
0140	907-823-A001	Preformed Joint Seal, Type I	2,576.000	LF	45.00	39.25	31.00
0150	907-823-A002	Preformed Joint Seal, Type II	211.000	LF	50.00	45.00	54.00
0160	907-823-B001	Saw Cut, Type I	4,956.000	LF	14.00	9.00	8.00
0170	907-823-B002	Saw Cut, Type II	423.000	LF	14.00	11.50	9.00
0180	907-824-PP095	Bridge Repair, Base Plate Replacement	34.000	EA	6,000.00	9,000.00	4,850.00
0190	907-824-PP095	Bridge Repair, Bearing Replacement	12.000	EA	5,000.00	6,500.00	3,300.00
0200	907-824-PP095	Bridge Repair, Pressure Wash and Clean Bent	58.000	EA	1,000.00	1,000.00	1,050.00
0210	907-824-PP101	Bridge Repair, Epoxy Repair	28.000	CF	2,500.00	1,655.00	1,950.00
0220	907-845-A002	Coating Existing Structural Steel	1.000	LS	1,352,000.00	1,371,385.00	2,048,000.00

Bridge Painting on I-20 & I-55 at the Pearl River, known as Federal Aid Project Nos. BR-0055-02(247) / 107402301 & STP-0020-01 (222) / 107138307 in Rankin & Hinds Counties.					Spartan Contracting, LLC		
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$2,990,753.15					\$3,797,000.00		
Ref#	Item	Item Description	Item Qty	Units	13		
0010	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	189.000	SF	6.00		
0020	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,544.000	SF	6.00		
0030	619-E1001	Flashing Arrow Panel, Type C	7.000	EA	1,000.00		
0040	619-G4001	Barricades, Type III, Single Faced	156.000	LF	33.00		
0050	619-G5001	Free Standing Plastic Drums	429.000	EA	30.00		
0060	619-G7001	Warning Lights, Type "B"	64.000	EA	300.00		
0070	620-A001	Mobilization	1.000	LS	175,000.00		
0080	907-618-A001	Maintenance of Traffic	1.000	LS	300,000.00		
0090	907-619-E3001	Changeable Message Sign	10.000	EA	7,000.00		
0100	202-B298	Removal of Existing Joint Material	1,051.000	LF	49.00		
0110	202-B307	Removal of Bridge Deck	43.000	SY	260.00		
0120	808-A001	Joint Preparation	5,575.000	LF	22.00		
0130	907-804-A001	Bridge Concrete, Class AA	9.000	CY	5,750.00		
0140	907-823-A001	Preformed Joint Seal, Type I	2,576.000	LF	38.00		
0150	907-823-A002	Preformed Joint Seal, Type II	211.000	LF	44.00		
0160	907-823-B001	Saw Cut, Type I	4,956.000	LF	9.00		
0170	907-823-B002	Saw Cut, Type II	423.000	LF	11.00		
0180	907-824-PP095	Bridge Repair, Base Plate Replacement	34.000	EA	5,000.00		
0190	907-824-PP095	Bridge Repair, Bearing Replacement	12.000	EA	3,500.00		
0200	907-824-PP095	Bridge Repair, Pressure Wash and Clean Bent	58.000	EA	1,000.00		
0210	907-824-PP101	Bridge Repair, Epoxy Repair	28.000	CF	2,000.00		
0220	907-845-A002	Coating Existing Structural Steel	1.000	LS	2,477,876.00		