

Call 03 Bridge Repair on US 98E Pearl River Bridge, known as Federal Aid Project No. BR-0014-02(076) / 107429301 in Marion County.

Q1. Is the material for pay item 907-824-PP006 provided by MDOT?

A1. The thrie-beam guardrail is provided. Please refer to Notice to Bidders #133.

Q2. On sheet 8004 in the section E-E detail it calls for the guardrail assembly post to be a W6x16 beam. In that same section below the hole punch detail of the assembly post it calls for the beam to be W6x12. Please clarify if the material is W6x16 or W6x12.

A2. W6x16 is correct.