

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Key, LLC	Riverside Construction Company, Inc.	T. L. Wallace Construction, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$3,821,682.25	\$4,711,210.50	\$4,718,511.55
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	201-A001	Clearing and Grubbing	1.000	LS	13,500.00	25,000.00	200,000.00
0020	228-A004	Erosion Control Blanket, Type IV	500.000	SY	4.00	4.00	4.00
0030	234-A001	Temporary Silt Fence	1,000.000	LF	6.50	3.50	4.00
0040	234-C001	Super Silt Fence	500.000	LF	12.50	10.00	11.00
0050	234-F001	Turbidity Barrier	1,200.000	LF	20.00	20.00	13.00
0060	237-A002	Wattles, 20"	500.000	LF	5.00	5.00	5.00
0070	607-B034	84" Type II Chain Link Fence, Class I	100.000	LF	38.00	7.50	42.00
0080	607-G004	Gate, 4' x 7' Chain Link	1.000	EA	700.00	300.00	770.00
0090	607-G124	Gate, 24' x 7' Double Chain Link	1.000	EA	1,200.00	1,800.00	1,320.00
0100	607-P1024	Line Post, 10' x 2" Galvanized Steel	5.000	EA	205.00	80.00	225.00
0110	607-P2001	Brace Post, 11' 6" x 2 1/2" Galvanized Steel	2.000	EA	437.00	100.00	480.00
0120	607-P3014	Gate Post, 11' x 3 1/2" Galvanized Steel	4.000	EA	437.00	140.00	505.00
0130	618-A001	Maintenance of Traffic	1.000	LS	25,000.00	15,000.00	115,000.00
0140	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	48.000	SF	5.50	9.00	6.00
0150	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,072.000	SF	5.50	9.00	6.00
0160	619-E1001	Flashing Arrow Panel, Type C	4.000	EA	1,350.00	2,470.00	1,500.00
0170	619-G4005	Barricades, Type III, Single Faced	48.000	LF	14.00	20.00	15.00
0180	619-G5001	Free Standing Plastic Drums	86.000	EA	45.00	77.00	50.00
0190	619-G7001	Warning Lights, Type "B"	16.000	EA	85.00	570.00	95.00
0200	620-A001	Mobilization	1.000	LS	250,000.00	470,000.00	385,000.00
0210	804-A001	Bridge Concrete, Class AA	212.000	CY	1,350.00	1,750.00	815.00
0220	805-A001	Reinforcement	22,977.000	LBS	2.25	1.50	1.15
0230	808-A001	Joint Preparation	5,640.000	LF	2.50	2.50	2.70
0240	815-A009	Loose Riprap, Size 500	18,800.000	TON	65.00	81.03	60.00
0250	815-E001	Geotextile under Riprap	11,600.000	SY	2.50	2.60	2.25
0260	907-823-A001	Preformed Joint Seal, Type I	2,820.000	LF	25.00	25.00	27.00

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Key, LLC	Riverside Construction Company, Inc.	T. L. Wallace Construction, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$3,821,682.25	\$4,711,210.50	\$4,718,511.55
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0270	907-823-B001	Saw Cut, Type I	5,640.000	LF	5.00	5.00	5.50
0280	907-824-PP005	Bridge Repair, Epoxy Repair, Per Plans Epoxy Repair, Per Plans	30.000	CF	1,750.00	1,750.00	1,975.00
0290	907-824-PP006	Bridge Repair, Bearing Replacement, Per Plans Bearing Replacement, Per Plans	410.000	EA	1,850.00	2,865.00	3,200.00
0300	907-824-PP006	Bridge Repair, Cap Cleaning Cap Cleaning	51.000	EA	700.00	950.00	1,090.00
0310	907-824-PP008	Bridge Repair, FRP Wrap, Per Plans FRP Wrap, Per Plans	545.000	LF	205.00	205.00	205.00
0320	907-845-A001	Coating Existing Structural Steel	1.000	LS	805,000.00	664,424.00	945,000.00

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Century Construction & Realty, Inc.	Tanner Construction Company, Inc.	Southern Road & Bridge, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$4,769,328.80	\$5,326,283.25	\$5,729,030.00
Ref#	Item	Item Description	Item Qty	Units	4	5	6
0010	201-A001	Clearing and Grubbing	1.000	LS	280,000.00	170,000.00	25,000.00
0020	228-A004	Erosion Control Blanket, Type IV	500.000	SY	4.55	4.00	5.00
0030	234-A001	Temporary Silt Fence	1,000.000	LF	3.98	3.50	3.00
0040	234-C001	Super Silt Fence	500.000	LF	11.37	10.00	8.00
0050	234-F001	Turbidity Barrier	1,200.000	LF	62.50	18.00	15.00
0060	237-A002	Wattles, 20"	500.000	LF	5.68	5.00	17.00
0070	607-B034	84" Type II Chain Link Fence, Class I	100.000	LF	43.18	40.00	45.00
0080	607-G004	Gate, 4' x 7' Chain Link	1.000	EA	795.43	1,500.00	100.00
0090	607-G124	Gate, 24' x 7' Double Chain Link	1.000	EA	1,363.59	2,000.00	1,500.00
0100	607-P1024	Line Post, 10' x 2" Galvanized Steel	5.000	EA	232.95	500.00	300.00
0110	607-P2001	Brace Post, 11' 6" x 2 1/2" Galvanized Steel	2.000	EA	496.58	500.00	500.00
0120	607-P3014	Gate Post, 11' x 3 1/2" Galvanized Steel	4.000	EA	519.30	500.00	500.00
0130	618-A001	Maintenance of Traffic	1.000	LS	90,000.00	120,000.00	400,000.00
0140	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	48.000	SF	6.26	9.00	10.00
0150	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,072.000	SF	6.25	9.00	10.00
0160	619-E1001	Flashing Arrow Panel, Type C	4.000	EA	1,534.05	2,470.00	2,500.00
0170	619-G4005	Barricades, Type III, Single Faced	48.000	LF	15.91	20.00	20.00
0180	619-G5001	Free Standing Plastic Drums	86.000	EA	51.14	77.00	77.00
0190	619-G7001	Warning Lights, Type "B"	16.000	EA	96.59	570.00	570.00
0200	620-A001	Mobilization	1.000	LS	475,000.00	550,000.00	500,000.00
0210	804-A001	Bridge Concrete, Class AA	212.000	CY	945.29	1,400.00	2,000.00
0220	805-A001	Reinforcement	22,977.000	LBS	1.10	1.25	4.00
0230	808-A001	Joint Preparation	5,640.000	LF	5.68	2.50	8.00
0240	815-A009	Loose Riprap, Size 500	18,800.000	TON	62.00	55.00	82.00
0250	815-E001	Geotextile under Riprap	11,600.000	SY	2.60	1.00	3.00
0260	907-823-A001	Preformed Joint Seal, Type I	2,820.000	LF	28.41	25.00	35.00

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Century Construction & Realty, Inc.	Tanner Construction Company, Inc.	Southern Road & Bridge, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$4,769,328.80	\$5,326,283.25	\$5,729,030.00
Ref#	Item	Item Description	Item Qty	Units	4	5	6
0270	907-823-B001	Saw Cut, Type I	5,640.000	LF	5.68	5.00	10.00
0280	907-824-PP005	Bridge Repair, Epoxy Repair, Per Plans Epoxy Repair, Per Plans	30.000	CF	1,097.71	915.00	1,400.00
0290	907-824-PP006	Bridge Repair, Bearing Replacement, Per Plans Bearing Replacement, Per Plans	410.000	EA	2,220.00	3,700.00	2,500.00
0300	907-824-PP006	Bridge Repair, Cap Cleaning Cap Cleaning	51.000	EA	654.80	2,500.00	1,000.00
0310	907-824-PP008	Bridge Repair, FRP Wrap, Per Plans FRP Wrap, Per Plans	545.000	LF	315.31	470.00	200.00
0320	907-845-A001	Coating Existing Structural Steel	1.000	LS	1,090,000.00	990,000.00	1,200,000.00

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Olympus Painting Contractors, Inc.	Joe McGee Construction Company, Inc.	
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$5,985,655.25	\$6,081,124.00	
Ref#	Item	Item Description	Item Qty	Units	7	8	
0010	201-A001	Clearing and Grubbing	1.000	LS	135,000.00	310,000.00	
0020	228-A004	Erosion Control Blanket, Type IV	500.000	SY	6.50	5.00	
0030	234-A001	Temporary Silt Fence	1,000.000	LF	8.00	5.00	
0040	234-C001	Super Silt Fence	500.000	LF	12.00	14.00	
0050	234-F001	Turbidity Barrier	1,200.000	LF	47.00	25.75	
0060	237-A002	Wattles, 20"	500.000	LF	6.00	7.50	
0070	607-B034	84" Type II Chain Link Fence, Class I	100.000	LF	30.00	20.00	
0080	607-G004	Gate, 4' x 7' Chain Link	1.000	EA	525.00	350.00	
0090	607-G124	Gate, 24' x 7' Double Chain Link	1.000	EA	1,560.00	1,000.00	
0100	607-P1024	Line Post, 10' x 2" Galvanized Steel	5.000	EA	65.00	40.00	
0110	607-P2001	Brace Post, 11' 6" x 2 1/2" Galvanized Steel	2.000	EA	125.00	75.00	
0120	607-P3014	Gate Post, 11' x 3 1/2" Galvanized Steel	4.000	EA	125.00	75.00	
0130	618-A001	Maintenance of Traffic	1.000	LS	225,000.00	212,000.00	
0140	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	48.000	SF	15.00	9.00	
0150	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	1,072.000	SF	15.00	9.00	
0160	619-E1001	Flashing Arrow Panel, Type C	4.000	EA	2,250.00	2,500.00	
0170	619-G4005	Barricades, Type III, Single Faced	48.000	LF	18.50	20.00	
0180	619-G5001	Free Standing Plastic Drums	86.000	EA	40.00	80.00	
0190	619-G7001	Warning Lights, Type "B"	16.000	EA	200.00	600.00	
0200	620-A001	Mobilization	1.000	LS	250,000.00	500,000.00	
0210	804-A001	Bridge Concrete, Class AA	212.000	CY	1,800.00	1,750.00	
0220	805-A001	Reinforcement	22,977.000	LBS	4.25	2.00	
0230	808-A001	Joint Preparation	5,640.000	LF	10.80	2.50	
0240	815-A009	Loose Riprap, Size 500	18,800.000	TON	74.40	100.00	
0250	815-E001	Geotextile under Riprap	11,600.000	SY	3.18	2.50	
0260	907-823-A001	Preformed Joint Seal, Type I	2,820.000	LF	39.60	25.00	

Bridge Repair on SR 25 at Pearl River, Bridge Nos. 1.7A & 1.7B, known as Federal Aid Project Nos. BR-0056-01(093) / 107404301 & BR-0056-01(093) / 107404302 in Hinds & Rankin Counties.					Olympus Painting Contractors, Inc.	Joe McGee Construction Company, Inc.	
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$5,373,089.20					\$5,985,655.25	\$6,081,124.00	
Ref#	Item	Item Description	Item Qty	Units	7	8	
0270	907-823-B001	Saw Cut, Type I	5,640.000	LF	13.20	5.00	
0280	907-824-PP005	Bridge Repair, Epoxy Repair, Per Plans Epoxy Repair, Per Plans	30.000	CF	1,050.00	1,750.00	
0290	907-824-PP006	Bridge Repair, Bearing Replacement, Per Plans Bearing Replacement, Per Plans	410.000	EA	3,500.00	2,865.00	
0300	907-824-PP006	Bridge Repair, Cap Cleaning Cap Cleaning	51.000	EA	4,000.00	1,300.00	
0310	907-824-PP008	Bridge Repair, FRP Wrap, Per Plans FRP Wrap, Per Plans	545.000	LF	325.00	250.00	
0320	907-845-A001	Coating Existing Structural Steel	1.000	LS	1,250,000.00	1,100,000.00	