

| Bridge Repair on US 98E Pearl River Bridge, known as Federal Aid Project No. BR-0014-02(076) / 107429301 in Marion County. |               |  |           |       | T. L. Wallace Construction, Inc. | Tanner Construction Company, Inc. |  |
|--|---------------|--|-----------|-------|----------------------------------|-----------------------------------|--|
| MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$547,342.00   |               |  |           |       | \$351,637.00                     | \$390,512.00                      |  |
| Ref#   | Item          | Item Description   | Item Qty  | Units | 1                                | 2                                 |  |
| 0010   | 202-B150      | Removal of Guard Rail Including Post, Blockouts & Hardware   | 50.000    | LF    | 9.00                             | 8.00                              |  |
| 0020   | 202-B240      | Removal of Traffic Stripe  | 2,100.000 | LF    | 1.10                             | 2.00                              |  |
| 0030   | 606-B013      | Guard Rail, Class A, Type 1, Thrie Beam, Transition Section  | 14.000    | LF    | 28.00                            | 25.00                             |  |
| 0040   | 618-A001      | Maintenance of Traffic   | 1.000     | LS    | 35,000.00                        | 30,000.00                         |  |
| 0050   | 618-B001      | Additional Construction Signs  | 1.000     | SF    | 10.00                            | 10.00                             |  |
| 0060   | 619-F1001     | Concrete Median Barrier, Precast   | 1,250.000 | LF    | 43.00                            | 40.00                             |  |
| 0070   | 619-F2001     | Remove and Reset Concrete Median Barrier, Precast  | 1,250.000 | LF    | 12.00                            | 30.00                             |  |
| 0080   | 620-A001      | Mobilization   | 1.000     | LS    | 35,000.00                        | 35,000.00                         |  |
| 0090   | 627-C001      | Red-Clear Reflective Raised Markers  | 10.000    | EA    | 55.00                            | 5.00                              |  |
| 0100   | 907-624-A002  | 6" Inverted Profile Thermoplastic Traffic Stripe, Skip White   | 700.000   | LF    |                                  |                                   |  |
| 0110   | 907-624-B002  | 6" Inverted Profile Thermoplastic Traffic Stripe, Continuous White   | 700.000   | LF    |                                  |                                   |  |
| 0120   | 907-624-D002  | 6" Inverted Profile Thermoplastic Traffic Stripe, Continuous Yellow  | 700.000   | LF    |                                  |                                   |  |
| 0130   | 628-A002      | 6" Cold Plastic Traffic Stripe, Skip White   | 700.000   | LF    | 5.25                             | 4.00                              |  |
| 0140   | 628-B001      | 6" Cold Plastic Traffic Stripe, Continuous White   | 700.000   | LF    | 5.25                             | 5.50                              |  |
| 0150   | 628-D002      | 6" Cold Plastic Traffic Stripe, Continuous Yellow  | 700.000   | LF    | 5.25                             | 5.50                              |  |
| 0160   | 907-824-PP006 | Bridge Repair, Guardrail Connection Assemblies Guardrail Connection Assemblies   | 230.000   | EA    | 710.00                           | 828.00                            |  |
| 0170   | 907-824-PP008 | Bridge Repair, Installation of Modified Tri-Beam Guardrail (Tri-Beam Provided By the State) Per Plans Installation of Modified Tri-Beam Guardrail (Tri-Beam Provided By the State) Per Plans | 1,394.000 | LF    | 25.00                            | 23.00                             |  |