

Call 10 Bridge Replacement on US 51, Bridge No. 205.4, known as Federal Aid Project No. BR-2901-00(033) / 105807301 in Grenada County.

Q1. Laminated pad (LP1) detail on Sheet 8013 calls for sloped plate in description, but none is shown. Please clarify.

A1. See addendum.

Q2. Sheet Number 8016 does not provide the skew angle of the detour bridge. Please confirm that the skew angle of the detour bridge is 0 degrees.

A2. The detour bridge is not skewed.

Q3. The detour bridge main span minimum length is listed as 70'-0" on sheet number 8016. Would MDOT be willing to allow a 62'-0" main span length considering the grade could be raised to still meet the minimum effective opening requirement?

A3. No.