

Call 06 Bridge Rehabilitation on SR 481 over Caney Creek, Bridge No. 9.3, known as Federal Aid Project No. BR-0331-00(014) / 107866301 in Smith County.

Q1. According to Special Provision No. 907-417-1, the surface of the Polymer Cement Surface System "may be patterned and/or monolithic as specified in the plans, or as directed by the Engineer." The plans do not specify whether the PCSS is to be patterned and/or monolithic. Please advise as to whether the PCSS is to be patterned and/or monolithic on this project.

A1. See addendum.

Q2. Please provide a breakdown of the quantities for Pay Item No 907-824-PP003 - Bridge Repair, Removal of Bridge Deck. The full depth repair at the bridge joints does not total up to the plan quantity, is there any additional full depth repair anticipated?

A2. See addendum.

Q3. Please confirm that additional quantity of Bridge Deck Overlay Concrete will be paid for due to unsound concrete or full depth repair specified by the Engineer.

A3. Refer to Working Number 2 of 6, Sheet 8003 in the plans.

Q4. Is it the intent of the Department to require dewatering of the channel prior to placing Rip Rap?

A4. No.