

**Call 12 Bridge Replacement on US 51 from Pope to Courtland (Bridge Nos. 242.9 & 243.2), known as Federal Aid Project No. BR-2901-00(028) / 103333301 in Panola County.**

Q1. 1.) Bearing pad type LP1 & LP2 on bridge drawing A32 & bearing pad type LP2 on bridge drawing B25 show identical layouts but call out different thicknesses (2.5" vs. 2.5625"). Please clarify which thickness is required. 2.) Bearing pad type LP2 on bridge drawing A32 calls for 2 internal layers but shows 4 shims. Please confirm pad requires 3 internal layers.

A1. 1.) The thicknesses in the plans are correct. 2.) See addendum.