

| | | | | | | | |
|--|---------------|-------------------------------------|-----------|-------|-----------------------|-------------------|--|
| Bridge Preventative Maintenance on SR 184 (Br. No. 122.6), SR 37 (Br. No. 4.3), SR 35 (Br. No. 51.2), SR 541 (Br. Nos. 10.4 & 21.3), SR 13 (Br. Nos.103.6, 104.2, 104.3 & 106.4), SR 540 (Br. No. 1.1), SR 43 (Br. Nos.7.3,121.4 & 126.1) & SR 28 (Br. Nos. 98.2, 106.3, 107.2, 107.4,107.9, 116.3 & 116.7), known as Federal Aid Project Nos. STBG-9999-07(384) / 1086203071, 3072, 3073, & 3074 in Covington, Jefferson Davis, Simpson & Smith Counties. | | | | | Sunbelt Sealing, Inc. | A-1 Sealing, Inc. | |
| MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$496,296.00 | | | | | \$494,808.00 | \$495,394.00 | |
| Ref# | Item | Item Description | Item Qty | Units | 1 | 2 | |
| 0010 | 202-B169 | Removal of Joint Material | 624.000 | LF | 20.00 | 30.00 | |
| 0020 | 618-A001 | Maintenance of Traffic | 1.000 | LS | 50,000.00 | 53,000.00 | |
| 0030 | 618-B001 | Additional Construction Signs | 4.000 | SF | 10.00 | 10.00 | |
| 0040 | 620-A001 | Mobilization | 1.000 | LS | 62,000.00 | 10,000.00 | |
| 0050 | 907-808-A002 | Joint Repair | 568.000 | LF | 10.00 | 25.00 | |
| 0060 | 907-808-A003 | Joint Repair Without Epoxy | 8,618.000 | LF | 1.00 | 2.00 | |
| 0070 | 907-823-A001 | Preformed Joint Seal, Type I | 4,704.000 | LF | 21.00 | 22.00 | |
| 0080 | 907-823-A002 | Preformed Joint Seal, Type II | 370.000 | LF | 30.00 | 27.00 | |
| 0090 | 907-823-B001 | Saw Cut, Type I | 9,408.000 | LF | 7.00 | 10.00 | |
| 0100 | 907-823-B002 | Saw Cut, Type II | 740.000 | LF | 8.00 | 11.00 | |
| 0110 | 907-824-PP006 | Bridge Repair, Cap Cleaning | 81.000 | EA | 1,730.00 | 1,500.00 | |
| 0120 | 907-824-PP007 | Bridge Repair, Elastomeric Concrete | 9.000 | CY | 3,800.00 | 5,000.00 | |