

Call 04 Bridge Preventative Maintenance on SR 365 (Bridge Nos. 17.8 & 18.1), known as Federal Aid Project No. STBG-9999-01(402) / 108620301 in Tishomingo County.

Q1. The Bearing Replacement drawing shows a table for NP1, NP2 and NP3 pads. However, the bearing layout only shows NP1 pads. Are there any NP2 or NP3 pads required?

A1. See addendum.

Q2. Are there any as-builts available for this project?

A2. As-builts can be downloaded at the following link:

<https://file-exchange.mdot.state.ms.us/dl/?f=8bf55e525f839d82fff60c57edc17ab21c913de9>