Call 10 Intersection Improvements on various routes throughout the District, known as Federal Aid Project No. HSIP-9999-03(017) / 107793301 in District 3.

- Q1. Sheet number 4002 has a symbol "PB" which is a Pull Box. There is a detail on Sheet Number 4005 for a Pull Box but there is no Pay Item for it. Also, Sheet 4003 has (3) Junction Boxes which is a pay item 682-E002 but there is not a detail for what type of box is needed. Can we use a polymer concrete box for all (4) of these boxes, which would be the same as the one we will be using as shown on Sheet 4006 for 682-E003 Underground Junction Box with Concrete Pad? It would have the same 6" concrete lip around it as shown on Sheet 4005 but just a polymer concrete box.
- A1. The Pull Box (PB) designation is in error and is to be disregarded. A Junction Box (JB) should be installed in that location. Polymer concrete Junction Boxes for Pay Item 682-E002 will be allowed.