

**Call 02 Bridge Repairs on US 61 over Black Lake Bayou (Bridge Nos. 264.4A & 264.4B), known as Federal Aid Project No. NHPP-0009-04(042) / 109497301 in Coahoma County.**

Q1. Will MDOT accept 907-828-1 Hybrid Polymer Concrete as an alternative to 907-417-1 Polymer Cement Surface System?

A1. No.

Q2. On sheet 8009 The existing bearing assembly detail states that the beveled anchor plate is to remain in place. On the replacement bearing detail it states that the pad is to be vulcanized to the beveled anchor plate. It is not possible to vulcanize the bearing pad to the anchor plate in this case, please verify those notes.

A2. The note is in error and is to be disregarded.

Q3. Will hydrodemolition be allowed for the removal of bridge deck in lieu of using 30 lb hammers?

A3. Yes, in accordance with Special Provision 907-202-4.