

Call 06 Bridge Repair on Airport Road over I-59 (Bridge No. 75.0), known as Federal Aid Project No. STBG-0059-02(120) / 109530301 in Jones County.

Q1. Can MDOT please verify that the project is located at Terminal Drive (Bridge 75.0) over I-59 and not Airport Drive over I-59 (which is Bridge 92.5)?

A1. The project is located at Terminal Drive (Bridge 75.0) over I-59.

Q2. Can MDOT please provide As-Built drawings for the structure?

A2. As built drawings may be downloaded here: <https://file-exchange.mdot.state.ms.us/dl/?f=3d472accbe2dc411e4eec9e1d589f500595aa0af>

Q3. Item no. 202-B169 Removal of Existing Joint Material Includes Removal of Joint Armor. There is an item no. 907-808-A003 Joint Repair Without Epoxy. Should there be an item set up for Epoxy repair?

A3. No.