

Call 08 Bridge Repair on US 49W at the Sunflower River (Bridge Nos. 255.2 & 255.2B), known as Federal Aid Project No. STBG-0072-04(030) / 109303301 in Sunflower County.

- Q1. Line No. 0770 has been included to install 82 LF of FRP wrap, however, there is no reference to this scope of work in the plans nor have any details been included. Can MDOT please provide more information on where the FRP wrap gets installed?
- A1. FRP wrap will not be needed. See addendum.
- Q2. Special Provision 907-202-4 states that rotomilling of the existing concrete bridge deck prior to hydrodemolition will not be allowed. However, the rotomilling plan note on Sheet 8005 states rotomilling of the bridge deck will be allowed. Can MDOT please confirm that the contractor will be allowed to mill the existing concrete bridge deck for both structures prior to hydrodemolition?
- A2. See addendum.
- Q3. Confirm pay items numbers 200, 210, and 220 are supposed to be alternates?
- A3. See addendum.