

Call 05 Remove & Replace OGFC on approximately 9 miles of I-55 from US 98W to the bridge south of the Bouge Chitto Interchange, known as Federal Aid Project Nos. IM-0055-01(130) / 109475301 & IM-0055-01(131) / 109478301 in Lincoln & Pike Counties.

Q1. There is no pay item for 907-402-B001 Bituminous Tack Coat that typically goes with 907-402-A002 Open Graded Friction Course, 9.5-mm Mixture. Will this be paid as 407-A001 Asphalt for Tack Coat?

A1. See addendum.