

Bridge Repair on US 278 (Bridge No. 121.7A), known as Federal Aid Project No. NHPP-0077-01(009) / 109646301 in Lee County.					Talbot Brothers Contracting Co., Inc.	Phillips Contracting Co., Inc.	Key, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$678,830.50					\$567,798.00	\$637,485.00	\$729,144.60
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	619-A1007	Temporary Traffic Stripe, Continuous White, Type 1 or 2 Tape	627.000	LF	5.00	6.25	5.50
0020	619-A2008	Temporary Traffic Stripe, Continuous Yellow, Type 1 or 2 Tape	627.000	LF	5.00	6.25	5.50
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	16.000	SF	10.00	12.50	11.00
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	48.000	SF	10.00	12.50	11.00
0050	619-E1001	Flashing Arrow Panel, Type C	1.000	EA	2,000.00	2,500.00	2,155.00
0060	619-F1001	Concrete Median Barrier, Precast	580.000	LF	87.00	75.00	110.00
0070	619-G4005	Barricades, Type III, Single Faced	24.000	LF	24.00	30.00	26.00
0080	619-G5001	Free Standing Plastic Drums	32.000	EA	40.00	50.00	45.00
0090	619-G7001	Warning Lights, Type "B"	3.000	EA	150.00	187.50	165.00
0100	620-A001	Mobilization	1.000	LS	78,430.00	61,125.00	71,000.00
0110	907-618-A001	Maintenance of Traffic	1.000	LS	32,900.00	30,625.00	65,000.00
0120	907-626-A008	6" Thermoplastic Double Drop Traffic Stripe, Skip White	480.000	LF	6.00	7.50	6.50
0130	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	960.000	LF	6.00	7.50	6.50
0140	907-626-F004	6" Thermoplastic Double Drop Edge Stripe, Continuous Yellow	960.000	LF	6.00	7.50	6.50
0150	907-627-K001	Red-Clear Reflective High Performance Raised Markers	6.000	EA	20.00	25.00	22.00
0160	907-808-A003	Joint Repair Without Epoxy	186.000	LF	1.00	1.25	1.10
0170	907-823-A001	Preformed Joint Seal, Type I	93.000	LF	50.00	62.50	55.00
0180	907-823-B001	Saw Cut, Type I	186.000	LF	1.00	7.50	6.50
0190	907-824-A003	General Epoxy Repair	174.000	SF	200.00	240.00	650.00
0200	907-824-B003	FRP Wrap, Bi-directional	174.000	SF	175.00	350.00	165.00
0210	907-824-PP004	Bridge Repair, Remove and Replace Bridge Deck, Railing, and Beam	1.000	LS	288,000.00	340,000.00	344,500.00
0220	907-824-PP008	Bridge Repair, New Construction of Riser, Per Plans	11.000	LF	1,000.00	815.00	562.00
0230	907-824-PP008	Bridge Repair, Removal of Riser, Per Plans	11.000	LF	1,000.00	1,000.00	207.00

Bridge Repair on US 278 (Bridge No. 121.7A), known as Federal Aid Project No. NHPP-0077-01(009) / 109646301 in Lee County.					Century Construction Group, Inc.		
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$678,830.50					\$808,588.00		
Ref#	Item	Item Description	Item Qty	Units	4		
0010	619-A1007	Temporary Traffic Stripe, Continuous White, Type 1 or 2 Tape	627.000	LF	5.00		
0020	619-A2008	Temporary Traffic Stripe, Continuous Yellow, Type 1 or 2 Tape	627.000	LF	5.00		
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	16.000	SF	12.00		
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	48.000	SF	12.00		
0050	619-E1001	Flashing Arrow Panel, Type C	1.000	EA	2,500.00		
0060	619-F1001	Concrete Median Barrier, Precast	580.000	LF	60.00		
0070	619-G4005	Barricades, Type III, Single Faced	24.000	LF	29.00		
0080	619-G5001	Free Standing Plastic Drums	32.000	EA	50.00		
0090	619-G7001	Warning Lights, Type "B"	3.000	EA	180.00		
0100	620-A001	Mobilization	1.000	LS	80,000.00		
0110	907-618-A001	Maintenance of Traffic	1.000	LS	25,000.00		
0120	907-626-A008	6" Thermoplastic Double Drop Traffic Stripe, Skip White	480.000	LF	7.00		
0130	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	960.000	LF	7.00		
0140	907-626-F004	6" Thermoplastic Double Drop Edge Stripe, Continuous Yellow	960.000	LF	7.00		
0150	907-627-K001	Red-Clear Reflective High Performance Raised Markers	6.000	EA	25.00		
0160	907-808-A003	Joint Repair Without Epoxy	186.000	LF	6.00		
0170	907-823-A001	Preformed Joint Seal, Type I	93.000	LF	40.00		
0180	907-823-B001	Saw Cut, Type I	186.000	LF	18.00		
0190	907-824-A003	General Epoxy Repair	174.000	SF	200.00		
0200	907-824-B003	FRP Wrap, Bi-directional	174.000	SF	170.00		
0210	907-824-PP004	Bridge Repair, Remove and Replace Bridge Deck, Railing, and Beam	1.000	LS	540,500.00		
0220	907-824-PP008	Bridge Repair, New Construction of Riser, Per Plans	11.000	LF	1,800.00		
0230	907-824-PP008	Bridge Repair, Removal of Riser, Per Plans	11.000	LF	600.00		