Call 02 Interchange Reconstruction on I-20 at Flowers, known as Federal Aid Project No. STBG-0020-01(262) / 103878301 in Warren County.

- Q1. 626.03.3 Retroreflectivity Requirements Will retroreflectivity measurements be required on this project?
- A1. No.
- Q2. Is item 400 (12.5-mm, HT Leveling) to be used for base repairs? If not, where will the 12.5-mm HT leveling be used given that there is a 19-mm, ST leveling item that looks to be intended for use in multi-layer leveling on the project?
- A2. The 12.5-mm leveling is set up to help maintain positive drainage between construction phases and as per the Project Engineer.
- Q3. The plans and EQ Sheet show a Type 4 cast in place barrier, however the pay item on the SQ Sheet is for a Type 1 barrier. Please clarify.
- A3. The Type 4 barrier is correct and will be paid for under Pay Item No. 615-A011, Concrete Type 1 Cast-in-Place Median Barrier, 42" High.