

Bridge Repair on Franklin Road over I-55 (Bridge No. 147.4) & on Old Wilson Road over I-55 (Bridge No. 160.9), known as Federal Aid Project No. STBG-9999-03(402) / 109690301 in Holmes County.					Key, LLC	Ste-Bil Grading Inc.	Gibson & Associates, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$988,708.55					\$898,455.50	\$955,128.00	\$1,055,351.60
Ref#	Item	Item Description	Item Qnty	Units	1	2	3
0010	202-B240	Removal of Traffic Stripe	1,300.000	LF	8.00	6.00	5.50
0020	619-A1002	Temporary Traffic Stripe, Continuous White	1,300.000	LF	2.70	3.00	2.75
0030	619-A2002	Temporary Traffic Stripe, Continuous Yellow	1,300.000	LF	2.70	3.00	2.75
0040	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	9.00	20.00	8.80
0050	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	717.000	SF	9.00	15.00	8.80
0060	619-G4001	Barricades, Type III, Double Faced	48.000	LF	25.00	25.00	25.30
0070	619-G4005	Barricades, Type III, Single Faced	192.000	LF	25.00	25.00	23.10
0080	619-G7001	Warning Lights, Type "B"	28.000	EA	161.00	200.00	165.00
0090	620-A001	Mobilization	1.000	LS	88,000.00	100,000.00	105,000.00
0100	907-618-A001	Maintenance of Traffic	1.000	LS	76,000.00	50,000.00	75,000.00
0110	907-619-E3001	Changeable Message Sign	4.000	EA	5,360.00	8,000.00	5,500.00
0120	907-626-B003	6" Thermoplastic Double Drop Traffic Stripe, Continuous White	1,300.000	LF	5.40	6.00	5.50
0130	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	1,300.000	LF	5.40	6.00	5.50
0140	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	16.000	EA	27.00	50.00	27.50
0150	202-B083	Removal of Concrete Slope Paving	13.000	SY	197.00	300.00	350.00
0160	815-D001	Concrete Slope Paving	2.000	CY	2,400.00	4,000.00	2,500.00
0170	907-417-A001	Polymer Cement Surface System	1,776.000	SY	109.00	113.00	112.00
0180	907-420-A001	Undersealing	2,500.000	LBS	6.45	8.00	7.43
0190	907-808-A002	Joint Repair	595.000	LF	1.10	5.00	2.20
0200	907-823-A002	Preformed Joint Seal, Type II	298.000	LF	43.00	35.00	35.20
0210	907-823-B002	Saw Cut, Type II	596.000	LF	7.50	15.00	11.00
0220	907-824-A003	General Epoxy Repair	20.000	SF	945.00	900.00	650.00
0230	907-824-C001	Cap Cleaning	10.000	EA	1,605.00	3,000.00	1,200.00
0240	907-824-D001	Bearing Replacements	72.000	EA	4,995.00	5,000.00	6,665.00
0250	907-824-PP008	Bridge Repair, Class 2 Spray Finish	1,348.000	LF	25.00	40.00	42.00

Bridge Repair on Franklin Road over I-55 (Bridge No. 147.4) & on Old Wilson Road over I-55 (Bridge No. 160.9), known as Federal Aid Project No. STBG-9999-03(402) / 109690301 in Holmes County.					Talbot Brothers Contracting Co., Inc.	Century Construction Group, Inc.	
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$988,708.55					\$1,058,745.04	\$1,069,892.75	
Ref#	Item	Item Description	Item Qnty	Units	4	5	
0010	202-B240	Removal of Traffic Stripe	1,300.000	LF	5.00	5.00	
0020	619-A1002	Temporary Traffic Stripe, Continuous White	1,300.000	LF	2.50	2.50	
0030	619-A2002	Temporary Traffic Stripe, Continuous Yellow	1,300.000	LF	2.50	2.50	
0040	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	8.08	10.00	
0050	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	717.000	SF	8.08	10.00	
0060	619-G4001	Barricades, Type III, Double Faced	48.000	LF	23.23	28.00	
0070	619-G4005	Barricades, Type III, Single Faced	192.000	LF	21.21	26.00	
0080	619-G7001	Warning Lights, Type "B"	28.000	EA	151.51	180.00	
0090	620-A001	Mobilization	1.000	LS	125,000.00	105,000.00	
0100	907-618-A001	Maintenance of Traffic	1.000	LS	100,000.00	88,000.00	
0110	907-619-E3001	Changeable Message Sign	4.000	EA	5,050.51	6,050.00	
0120	907-626-B003	6" Thermoplastic Double Drop Traffic Stripe, Continuous White	1,300.000	LF	5.00	6.00	
0130	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	1,300.000	LF	5.00	6.00	
0140	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	16.000	EA	25.00	30.50	
0150	202-B083	Removal of Concrete Slope Paving	13.000	SY	2,300.00	550.00	
0160	815-D001	Concrete Slope Paving	2.000	CY	5,000.00	5,000.00	
0170	907-417-A001	Polymer Cement Surface System	1,776.000	SY	112.82	123.00	
0180	907-420-A001	Undersealing	2,500.000	LBS	6.00	5.00	
0190	907-808-A002	Joint Repair	595.000	LF	6.00	6.25	
0200	907-823-A002	Preformed Joint Seal, Type II	298.000	LF	85.00	40.00	
0210	907-823-B002	Saw Cut, Type II	596.000	LF	6.00	14.50	
0220	907-824-A003	General Epoxy Repair	20.000	SF	1,000.00	750.00	
0230	907-824-C001	Cap Cleaning	10.000	EA	2,000.00	2,000.00	
0240	907-824-D001	Bearing Replacements	72.000	EA	5,035.00	6,150.00	
0250	907-824-PP008	Bridge Repair, Class 2 Spray Finish	1,348.000	LF	60.00	40.00	