

Call 07 Bridge Repair on Old Byram Road over I-55 (Bridge No. 86.4), known as Federal Aid Project No. STBG-9999-05(429) / 109682301 in Hinds County.

Q1. Can we have a detail for the "New Bars D" as shown in Detail D on Page 81?

A1. It is detailed on Page 81. It is located to the right of the "PLAN VIEW".

Q2. Can all pack rust and scale from bearing assemblies be removed using the method explained in 907-824.03.06-- Encapsulating Field Painting in lieu of abrasive blast cleaning as defined in SSPC-SP 10? Please advise.

A2. No.