

Bridge Repair on Old Byram Road over I-55 (Bridge No. 86.4), known as Federal Aid Project No. STBG-9999-05(429) / 109682301 in Hinds County.					Gibson & Associates, Inc.	Key, LLC	Hemphill Construction Company, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$352,276.78					\$566,193.00	\$598,542.20	\$734,886.05
Ref#	Item	Item Description	Item Qnty	Units	1	2	3
0010	619-A1002	Temporary Traffic Stripe, Continuous White	500.000	LF	1.10	1.10	1.25
0020	619-A2002	Temporary Traffic Stripe, Continuous Yellow	500.000	LF	1.10	1.10	1.25
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	8.80	9.00	9.25
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	399.000	SF	8.80	9.00	9.25
0050	619-G4001	Barricades, Type III, Double Faced	72.000	LF	25.30	25.00	26.50
0060	619-G4005	Barricades, Type III, Single Faced	96.000	LF	23.10	25.00	26.50
0070	619-G7001	Warning Lights, Type "B"	14.000	EA	148.50	150.00	155.00
0080	620-A001	Mobilization	1.000	LS	148,000.00	48,500.00	149,800.00
0090	907-618-A001	Maintenance of Traffic	1.000	LS	16,000.00	19,500.00	67,500.00
0100	907-619-E3001	Changeable Message Sign	6.000	EA	3,850.00	3,800.00	4,050.00
0110	907-626-B003	6" Thermoplastic Double Drop Traffic Stripe, Continuous White	500.000	LF	11.55	12.00	12.75
0120	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	500.000	LF	11.55	12.00	12.75
0130	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	6.000	EA	74.80	75.00	82.50
0140	202-B026	Removal of Bridge Deck	6.000	SY	500.00	1,290.00	2,750.00
0150	907-808-A002	Joint Repair	102.000	LF	40.00	1.10	1.15
0160	907-823-A002	Preformed Joint Seal, Type II	51.000	LF	120.00	55.00	58.00
0170	907-824-A003	General Epoxy Repair	104.000	SF	500.00	830.00	650.00
0180	907-824-C001	Cap Cleaning	2.000	EA	2,600.00	1,800.00	1,150.00
0190	907-824-F001	Encapsulating Field Painting	88.000	SF	1,265.00	1,275.00	325.00
0200	907-824-PP007	Bridge Repair, Elastomeric Concrete	1.000	CY	35,000.00	16,060.00	26,500.00
0210	907-824-PP008	Bridge Repair, Endwall Repair	48.000	LF	725.00	700.00	935.00
0220	907-834-A001	Polyester Polymer Concrete Overlay	13.000	CY	8,000.00	17,000.00	21,395.00