

Bridge Repairs on Old US 11 over I-59 (Bridge No. 47.9) & Richburg Road over I-59 (Bridge Nos. 61.9A, & 61.9B), known as Federal Aid Project No. STBG-9999-06(405) / 109670301 in Lamar County.					Key, LLC	Gibson & Associates, Inc.	Century Construction Group, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$1,742,194.20					\$1,755,449.40	\$1,788,680.20	\$1,948,957.25
Ref#	Item	Item Description	Item Qnty	Units	1	2	3
0010	202-B169	Removal of Joint Material	942.000	LF	45.00	60.00	225.00
0020	202-B240	Removal of Traffic Stripe	3,120.000	LF	1.10	2.50	4.00
0030	619-A1002	Temporary Traffic Stripe, Continuous White	1,560.000	LF	3.00	2.75	1.00
0040	619-A2002	Temporary Traffic Stripe, Continuous Yellow	1,560.000	LF	3.00	2.75	1.00
0050	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	11.00	11.00	12.25
0060	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	576.000	SF	11.00	11.00	12.25
0070	619-G4001	Barricades, Type III, Double Faced	48.000	LF	26.00	25.00	28.75
0080	619-G4005	Barricades, Type III, Single Faced	96.000	LF	26.00	23.00	26.25
0090	620-A001	Mobilization	1.000	LS	173,000.00	176,000.00	195,000.00
0100	907-417-A001	Polymer Cement Surface System	1,776.000	SY	130.00	155.00	142.25
0110	907-420-A001	Undersealing	2,000.000	LBS	4.70	8.00	5.75
0120	907-618-A001	Maintenance of Traffic	1.000	LS	177,000.00	231,500.00	180,000.00
0130	907-619-E3001	Changeable Message Sign	4.000	EA	5,325.00	5,280.00	6,000.00
0140	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	1,560.000	LF	5.50	5.50	4.75
0150	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	1,560.000	LF	5.50	5.50	4.75
0160	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	20.000	EA	28.00	27.50	25.00
0170	907-808-A003	Joint Repair Without Epoxy	942.000	LF	2.20	1.10	2.50
0180	907-823-A001	Preformed Joint Seal, Type I	574.000	LF	36.00	55.00	35.00
0190	907-823-B001	Saw Cut, Type I	633.000	LF	11.00	8.00	12.25
0200	907-824-A003	General Epoxy Repair	36.000	SF	1,200.00	700.00	500.00
0210	907-824-B003	FRP Wrap, Bi-directional	540.000	SF	185.00	180.00	160.00
0220	907-824-C001	Cap Cleaning	15.000	EA	2,500.00	1,500.00	2,100.00
0230	907-824-D001	Bearing Replacements	96.000	EA	5,792.00	6,950.00	6,300.00
0240	907-824-PP007	Bridge Repair, Elastomeric Concrete	11.000	CY	12,500.00	3,600.00	12,000.00
0250	907-824-PP008	Bridge Repair, Endwall Repair	156.000	LF	1,000.00	500.00	820.00

Bridge Repairs on Old US 11 over I-59 (Bridge No. 47.9) & Richburg Road over I-59 (Bridge Nos. 61.9A, & 61.9B), known as Federal Aid Project No. STBG-9999-06(405) / 109670301 in Lamar County.					Joe McGee Construction Company, Inc.	Southern Road & Bridge, LLC	
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$1,742,194.20					\$2,093,145.00	\$2,793,845.00	
Ref#	Item	Item Description	Item Qnty	Units	4	5	
0010	202-B169	Removal of Joint Material	942.000	LF	39.70	55.00	
0020	202-B240	Removal of Traffic Stripe	3,120.000	LF	4.95	11.00	
0030	619-A1002	Temporary Traffic Stripe, Continuous White	1,560.000	LF	1.25	6.00	
0040	619-A2002	Temporary Traffic Stripe, Continuous Yellow	1,560.000	LF	1.25	6.00	
0050	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	12.40	15.00	
0060	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	576.000	SF	12.40	15.00	
0070	619-G4001	Barricades, Type III, Double Faced	48.000	LF	28.50	38.00	
0080	619-G4005	Barricades, Type III, Single Faced	96.000	LF	26.00	33.00	
0090	620-A001	Mobilization	1.000	LS	200,000.00	275,000.00	
0100	907-417-A001	Polymer Cement Surface System	1,776.000	SY	144.55	350.00	
0110	907-420-A001	Undersealing	2,000.000	LBS	5.60	11.00	
0120	907-618-A001	Maintenance of Traffic	1.000	LS	240,000.00	195,000.00	
0130	907-619-E3001	Changeable Message Sign	4.000	EA	5,950.00	5,900.00	
0140	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	1,560.000	LF	4.95	7.00	
0150	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	1,560.000	LF	4.95	7.00	
0160	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	20.000	EA	31.00	27.00	
0170	907-808-A003	Joint Repair Without Epoxy	942.000	LF	2.50	29.00	
0180	907-823-A001	Preformed Joint Seal, Type I	574.000	LF	34.70	195.00	
0190	907-823-B001	Saw Cut, Type I	633.000	LF	12.40	15.00	
0200	907-824-A003	General Epoxy Repair	36.000	SF	825.00	2,200.00	
0210	907-824-B003	FRP Wrap, Bi-directional	540.000	SF	205.00	305.00	
0220	907-824-C001	Cap Cleaning	15.000	EA	3,709.00	2,500.00	
0230	907-824-D001	Bearing Replacements	96.000	EA	6,900.00	5,500.00	
0240	907-824-PP007	Bridge Repair, Elastomeric Concrete	11.000	CY	16,115.00	30,000.00	
0250	907-824-PP008	Bridge Repair, Endwall Repair	156.000	LF	1,350.00	1,450.00	