

**Call 06 Bridge Repair on Peyton Road over I-55 (Bridge No.270.2), known as Federal Aid Project No. STBG-9999-02(404)/109700301 in Tate County.**

Q1. Will the contractor or MDOT be responsible for the friction testing of the HPCO?

A1. Friction testing will be performed by MDOT.

Q2. Can you provide the asbuilts for this bridge?

A2. They can be downloaded at the following link: <https://file-exchange.mdot.state.ms.us/dl/?f=5ac70d8e175fabaa723751adb0b3042aa1852a68>

Q3. Can MDOT provide a transition detail for the HPCO at the end of the bridge deck to the asphalt? The 3/4" overlay has caused a "bump" on previous projects getting on and off the bridge.

A3. See Addendum 1.