

Bridge Repair on Peyton Road over I-55 (Bridge No.270.2), known as Federal Aid Project No. STBG-9999-02(404)/109700301 in Tate County.					Talbot Brothers Contracting Co., Inc.	Century Construction Group, Inc.	Gibson & Associates, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$699,527.65					\$769,425.00	\$813,154.85	\$872,859.96
Ref#	Item	Item Description	Item Qnty	Units	1	2	3
0010	618-B001	Additional Construction Signs	1.000	SF	10.00	10.00	10.00
0020	619-A1002	Temporary Traffic Stripe, Continuous White	700.000	LF	3.00	3.50	3.30
0030	619-A2002	Temporary Traffic Stripe, Continuous Yellow	700.000	LF	3.00	3.50	3.30
0040	620-A001	Mobilization	1.000	LS	75,000.00	80,000.00	86,000.00
0050	630-A001	Standard Roadside Signs, Sheet Aluminum, 0.080" Thickness	5.000	SF	30.00	36.15	21.18
0060	630-A003	Standard Roadside Signs, Sheet Aluminum, 0.125" Thickness	18.000	SF	40.00	50.00	24.42
0070	630-C001	Square Tube Posts, 4.0 lb/ft	45.000	LF	60.00	72.50	60.50
0080	630-G005	Type 3 Object Markers, OM-3R or OM-3L, Post Mounted	4.000	EA	150.00	180.75	170.50
0090	907-618-A001	Maintenance of Traffic	1.000	LS	20,000.00	60,000.00	110,000.00
0100	907-619-E3001	Changeable Message Sign	2.000	EA	5,500.00	7,000.00	5,280.00
0110	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	700.000	LF	10.00	11.50	11.00
0120	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	700.000	LF	10.00	11.50	11.00
0130	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	4.000	EA	25.00	30.00	27.50
0140	202-B169	Removal of Joint Material	243.000	LF	154.00	275.00	55.00
0150	202-B208	Removal of Riprap	180.000	SY	88.00	125.00	225.00
0160	229-A001	Erosion Mat	250.000	SY	168.00	200.00	220.00
0170	612-A001	Flowable Fill, Excavatable	24.000	CY	2,000.00	1,325.00	1,150.00
0180	907-808-A003	Joint Repair Without Epoxy	195.000	LF	1.00	3.00	5.00
0190	907-823-A002	Preformed Joint Seal, Type II	100.000	LF	120.00	45.00	130.00
0200	907-823-B002	Saw Cut, Type II	192.000	LF	8.00	12.05	10.00
0210	907-824-A003	General Epoxy Repair	3.000	SF	2,000.00	1,250.00	1,500.00
0220	907-824-C001	Cap Cleaning	7.000	EA	2,000.00	1,500.00	3,200.00
0230	907-824-D001	Bearing Replacements	16.000	EA	12,000.00	12,750.00	9,600.00
0240	907-824-F001	Encapsulating Field Painting	68.000	SF	614.00	220.00	300.00
0250	907-824-PP008	Bridge Repair, Endwall Repair	48.000	LF	900.00	775.00	1,150.00
0260	907-828-A001	Hybrid Polymer Concrete Overlay	17.000	CY	11,000.00	10,825.00	13,750.00

Bridge Repair on Peyton Road over I-55 (Bridge No.270.2), known as Federal Aid Project No. STBG-9999-02(404)/109700301 in Tate County.					Ste-Bil Grading Inc.	Key, LLC	Mobley Contractors, Inc.
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$699,527.65					\$949,225.00	\$989,663.00	IRREGULAR \$993,576.30
Ref#	Item	Item Description	Item Qnty	Units	4	5	6
0010	618-B001	Additional Construction Signs	1.000	SF	10.00	10.00	10.00
0020	619-A1002	Temporary Traffic Stripe, Continuous White	700.000	LF	3.00	3.50	3.75
0030	619-A2002	Temporary Traffic Stripe, Continuous Yellow	700.000	LF	3.00	3.50	3.75
0040	620-A001	Mobilization	1.000	LS	125,000.00	89,000.00	73,722.30
0050	630-A001	Standard Roadside Signs, Sheet Aluminum, 0.080" Thickness	5.000	SF	30.00	33.00	24.60
0060	630-A003	Standard Roadside Signs, Sheet Aluminum, 0.125" Thickness	18.000	SF	40.00	44.00	27.75
0070	630-C001	Square Tube Posts, 4.0 lb/ft	45.000	LF	60.00	66.00	68.75
0080	630-G005	Type 3 Object Markers, OM-3R or OM-3L, Post Mounted	4.000	EA	200.00	175.00	193.75
0090	907-618-A001	Maintenance of Traffic	1.000	LS	25,000.00	42,000.00	155,746.98
0100	907-619-E3001	Changeable Message Sign	2.000	EA	7,500.00	6,000.00	6,000.00
0110	907-626-C011	6" Thermoplastic Double Drop Edge Stripe, Continuous White	700.000	LF	10.00	11.00	12.50
0120	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	700.000	LF	10.00	11.00	12.50
0130	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	4.000	EA	50.00	28.00	31.25
0140	202-B169	Removal of Joint Material	243.000	LF	25.00	90.00	184.40
0150	202-B208	Removal of Riprap	180.000	SY	100.00	150.00	133.36
0160	229-A001	Erosion Mat	250.000	SY	250.00	255.00	178.62
0170	612-A001	Flowable Fill, Excavatable	24.000	CY	500.00	1,300.00	1,238.22
0180	907-808-A003	Joint Repair Without Epoxy	195.000	LF	30.00	140.00	247.95
0190	907-823-A002	Preformed Joint Seal, Type II	100.000	LF	100.00	55.00	131.98
0200	907-823-B002	Saw Cut, Type II	192.000	LF	10.00	7.00	13.58
0210	907-824-A003	General Epoxy Repair	3.000	SF	2,000.00	1,250.00	8,093.43
0220	907-824-C001	Cap Cleaning	7.000	EA	3,000.00	2,500.00	2,226.65
0230	907-824-D001	Bearing Replacements	16.000	EA	12,500.00	22,500.00	13,223.92
0240	907-824-F001	Encapsulating Field Painting	68.000	SF	100.00	300.00	500.00
0250	907-824-PP008	Bridge Repair, Endwall Repair	48.000	LF	600.00	1,500.00	774.75
0260	907-828-A001	Hybrid Polymer Concrete Overlay	17.000	CY	22,500.00	10,000.00	11,455.96