

Bridge Repair on Old Byram Road over I-55 (Bridge No. 86.4), known as Federal Aid Project No. STBG-9999-05(429) / 109682301 in Hinds County.					Concrete Strategies, LLC	Gibson & Associates, Inc.	Key, LLC
MISSISSIPPI DEPARTMENT OF TRANSPORTATION: \$505,428.80					\$401,355.00	\$439,535.00	\$447,750.20
Ref#	Item	Item Description	Item Qty	Units	1	2	3
0010	619-A1002	Temporary Traffic Stripe, Continuous White	500.000	LF	3.00	1.10	1.10
0020	619-A2002	Temporary Traffic Stripe, Continuous Yellow	500.000	LF	3.00	1.10	1.10
0030	619-D1001	Standard Roadside Construction Signs, Less than 10 Square Feet	96.000	SF	10.00	8.80	9.00
0040	619-D2001	Standard Roadside Construction Signs, 10 Square Feet or More	399.000	SF	10.00	8.80	9.00
0050	619-G4001	Barricades, Type III, Double Faced	72.000	LF	30.00	25.30	26.00
0060	619-G4005	Barricades, Type III, Single Faced	96.000	LF	30.00	23.10	26.00
0070	619-G7001	Warning Lights, Type "B"	14.000	EA	155.00	148.50	150.00
0080	620-A001	Mobilization	1.000	LS	47,000.00	99,000.00	44,000.00
0090	907-618-A001	Maintenance of Traffic	1.000	LS	24,000.00	31,000.00	20,000.00
0100	907-619-E3001	Changeable Message Sign	6.000	EA	5,000.00	3,850.00	3,300.00
0110	907-626-B003	6" Thermoplastic Double Drop Traffic Stripe, Continuous White	500.000	LF	13.00	11.55	12.00
0120	907-626-E004	6" Thermoplastic Double Drop Traffic Stripe, Continuous Yellow	500.000	LF	13.00	11.55	12.00
0130	907-627-L001	Two-Way Yellow Reflective High Performance Raised Markers	6.000	EA	80.00	74.80	75.00
0140	202-B026	Removal of Bridge Deck	6.000	SY	700.00	500.00	1,290.00
0150	907-808-A002	Joint Repair	102.000	LF	20.00	21.00	1.10
0160	907-823-A002	Preformed Joint Seal, Type II	51.000	LF	75.00	120.00	55.00
0170	907-824-A003	General Epoxy Repair	104.000	SF	330.00	500.00	830.00
0180	907-824-C001	Cap Cleaning	2.000	EA	2,000.00	2,000.00	1,800.00
0190	907-824-F001	Encapsulating Field Painting	88.000	SF	360.00	400.00	230.00
0200	907-824-PP007	Bridge Repair, Elastomeric Concrete	1.000	CY	12,000.00	19,000.00	16,060.00
0210	907-824-PP008	Bridge Repair, Endwall Repair	48.000	LF	425.00	725.00	700.00
0220	907-834-A001	Polyester Polymer Concrete Overlay	13.000	CY	12,250.00	8,200.00	13,000.00