

Call 02 Bridge Repair on MS 4 over Tenn-Tom Waterway (Bridge No. 158.5), known as Federal Aid Project No. STBG-0007-01(107) / 110038301 in Tishomingo County.

- Q1. Plan sheet 8007 has notes and details concerning "907-808-A003 Joint Repair Without Epoxy". it would appear that Bid Item #390 includes the total quantity for this work., is that correct? Plan sheet 8008 also has notes and details concerning "907-808-A003 Joint Repair Without Epoxy" with different details. Could MDOT please confirm where this work will be paid for?
- A1. Both joint repair types will be paid under Pay Item No. 907-808-A003, Joint Repair Without Epoxy.
- Q2. Scope of Work Note 3 on Sheet 8003 says to replace the bearings at Bents 1,9,5 & 13. The Replacement Bearing Detail on Sheet 8006 Shows Bent 12. Please confirm that the bearings at Bent 12 are to be replaced.
- A2. Bent 12 Bearings shown on Sheet 8006 are to be replaced.