

Call 09 Bridge Repair on SR 433 over Mound Creek (Bridge No. 11.6), known as Federal Aid Project No. STBG-0510-00(012) / 110184301 in Yazoo County.

- Q1. NTB 8319 "Scope of Work" states in the last full paragraph on page 85 "All debris, including any material that has accumulated on the bridge deck or caps, shall become the property of the Contractor and shall be removed from the construction site and disposed of properly." **1.)** Can MDOT please clarify the number and location of caps that will require cleaning and could a pay item be added for this work? **2.)** Can MDOT please clarify the limits of the concrete debris that is to be removed as listed on Item 1. under the Scope of Work? Will it be only as necessary to access pile repair areas at Bent 2 and reshape slope or will it include all concrete debris beneath the bridge including the creek and opposite bank?
- A1. **1.)** See Addendum 1. **2.)** The Contractor will only be required to remove the concrete debris necessary for pile repairs and slope reshaping.