



01 ER-0006-03(043) / 108056301, ER-0006-03(043) / 108057301 & ER-0006-03(043) / 108058301 Itawamba

Slide Repairs on I-22 near Mile Marker 116 in the Fill Slope of the Westbound Lane, near Mile Marker 114.5 in the Backslope of the Eastbound Lane, and Mile Marker 115 in the Backslope of the Eastbound Lane

1	Century Construction Group, Inc. - Tupelo, MS	\$	1,060,566.20
2	Phillips Contracting Co., Inc. - Columbus, MS	\$	1,154,649.50

STATE ESTIMATE

\$	1,093,288.40
	2.99%

UNDER STATE ESTIMATE

02 ER-0022-04(064) / 108095301 Pontotoc

Slide Repair on West side of SR 15 South of SR 41

1	Ste-Bil Grading Inc. - Waterford, MS IRREGULAR	\$	393,497.50
2	Xcavators, Inc. - Falkner, MS	\$	436,066.50
3	A & B Construction, LLC - Thaxton, MS IRREGULAR	\$	439,304.00
4	Talbot Bros Contr Co, Inc & Talbot Bros Grading Co, Inc, AJV - Nesbit, MS	\$	489,709.00
5	Phillips Contracting Co., Inc. - Columbus, MS	\$	618,154.00

STATE ESTIMATE

\$	573,598.40
	23.98%

UNDER STATE ESTIMATE